

ATTESTED BY THE BERRIEN COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER MICHIGAN
PUBLIC ACT 345 OF 1990

[Signature]
A-21-98
For corners in

BERRIEN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

OCT 27 PM 1:06

BERNICE TRETNEYWAY
REGISTER OF DEEDS
BERRIEN COUNTY, MICHIGAN

	Barrien (County)	Located In:	Corner Code #
1. Public Land Survey		T <u>8S</u> R <u>19W</u>	<u>F-9</u>
		T <u> </u> R <u> </u>	<u> </u>
		T <u> </u> R <u> </u>	<u> </u>
		T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>

10/27/98 111#4092 A44
CORNER \$7.00
10/27/98 111#4092 A44
Register of Deeds Stamp & File Number
STATE REMON FEE \$2.00

4. Lot No. , Recorded Plat
5. Private Claims

I, V. J. Strebs, in a field survey on May 12, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	

A. Description of original monument and accessories and/or subsequent restoration:

NOT SET IN ORIGINAL SURVEYS.

JUNE 19, 1968 D.M. DREHER SET 1 1/4" X 2" IRON PIPE. (NO WITNESSES).

SURVEY &
REMONUMENTATION

NOV 20 1998

SECTION

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 3/4" IRON INSIDE 1 1/4" IRON PIPE.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 1" X 3 FT IRON PIPE IN MONUMENT BOX; WIT TAG IN R.R. TIE FENCE POST N55°W 35.60'; WIT TAG IN 18" WILLOW S75°W 51.52'; WIT TAG IN 12" WILLOW S80°W 65.37'; WIT TAG IN 24" TRIPLE WILLOW S85°W 85.04'.

THIS POSITION NOT ESTABLISHED BY ORIGINAL GOVERNMENT SURVEYORS. THIS MONUMENT IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE CORNER.

Signed by *[Signature]*
Surveyor's Michigan License No. 26469



Date 7-9-98

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN 28, 1971
REVISED MAY 14, 1975
REVISED JAN, 1983
REVISED OCT, 1995