LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Chippewa	Located In:	Corner Code#				
(County)	-					
1. Public Land Survey	TR TR		:			
2. Property Controlling in Section	S 5 T 41N R 5E S 5 T 41N R 5E S T R	1 8				
3. Miscellaneous Property in Sec.	S T R R		Registe	er of Deeds	Stamp & File	Number
4. Lot No. , Red	orded Plat		A B C	D E	F G H !	IJKLM
5. Private Claims			1 1			
	1 03/2	23/2010	2 -6	•	1-1-1-	
ı, Stephan J. Szyszkoski , in	a field survey on 8 03/2	23/2010 do hereby state	, T			11 12
that under requirements of P.A.	· • []		i			
above were in conformance with regulations and rules therefore as required in the current manual of survey						
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of				1, 1	15-	1,41,3
a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, g				20 3	, ,	23 24
so netablished manufacted recovered found as expressed below.				i l		
, c cacabianca, mananinanca, rocara	, , , , , , , , , , , , , , , , , , , ,		9			
NOTE: Not more than 2 corn	ers, all in the same town and range	. may be recorded	10 30			2623-
			11	Ţ. I.		
on and continuate.			12 31) 3 3 3 1	3-36-

A. Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 5) West 1/16 corner between Section 5 T41N-R05E and Section 32 T42N-R05E. 1974 - Established by G.R.Gabel RLS midway and on line between Section and Quarter corners 1331.27' west and east. Set 3"x4" alum. plate on a 1" steel angle 6" out of ground. Cedar 6" N88W 24', Spruce 10" N32W 17', Spruce 10" S36E 16'.

(8-Sec. 5) West 1/16 corner Section 5. 1874 - Established by G.R.Gabel RLS midway and on a straight line between Quarter corner 1287.94' west and Center of Section 1287.94' east. Set 3"x4" alum. plate on 1" steel angle. Aspen 6" S21E 9.4', Birch 3" N66W 12.6', Birch 6" N36E 31.5'.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (1-Sec. 5) The 1974 monument was not recovered. Found the 1974 witness trees in good condition but the 1974 measurements to these trees appear to have been roughly made, making the precise 1974 corner position unclear. Reestablished the position for the corner midway and on line between Section corner 1331.45' west and the unmonumented position for 1/4 corner D1 1331.45' east.
- (8-Sec. 5) The 1974 monument and accessories were not recovered. Reestablished the 1974 position midway and on a straight line between Quarter corner 1286.35' west and Center of Section 1286.35' east.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (1) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 12" W.Spruce S27E 15.45' old marks (1974 BT) 14" W.Spruce N23W 18.35' do do 10" Cedar N76W 24.6' do do 7" Cedar N36E 14.35' mrkd "W1/16 BT" Bearings are magnetic.
- (8) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
 Set measuring nail with MDNR tag in the side of:
 Power pole DMI 3452 S18E 17.3'
 14" Twin W.Birch S77W 21.65' no marks
 14" W.Spruce N65E 48.9' do
 NE corner of bldg is N12W 82.9'
 Metal sign post is N27W 1.2'
 Bearings are magnetic.

Signed by Stephie	1. Smx	zlest.	Date	07/27/2010	1	STEPHAN J.		
Surveyor's Michigan License No. For the Michigan	Department of N	33986 latural Resources	and Environmen	t, Forest Managem	ie it Đyi:	LAND SURVEYOR	*	
47370				ROVED BY MICHIGAN STATE BO	- T	33986 4 Aug. 90	14,	1971 1975
47371					•	Tised	d Jan., 1	