

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Chippewa

(County)

Located In:

Corner Code ##

RECEIVED FOR RECORD
 CHIPPEWA COUNTY
 STATE OF MICHIGAN

94 JUL 22 AM 11:11

J. Ryan Malick
 REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey T R
 $\frac{1}{4}$ Corner T 43N R 1E A-6
 Section Corner T 43N R 1E A-5
 T R
 2. Property Controlling S T R
 in Section S T R
 3. Miscellaneous S T R
 Property in Sec. S T R

4. Lot No. , Recorded Plat 5. Private Claims

I, Keith R. Waters, in a field survey on OCTOBER 2, 19 93,
 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
 current manual of survey instructions of the United States Department of the Interior, Bureau of Land
 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
 Court of Law; established, re-established, monumented, re-monumented, recovered, found as
 expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
 on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

(A-6) From N. Hill Notes, 5-7-91: Set $\frac{1}{4}$ Corner on line between section corners 2641.74'
 North and 2629.74' South. Location Determined by fence line West and brushed opening
 East. Preserved location prior to road construction with natural witnesses.

1992: Neil Hill reset $\frac{1}{2}$ " iron with cap #27447 (L.7, P.357) N70W 72.82' Power Pole, West
 75.67' Corner Fence Post, S65W 106.43' Southerly Gate Post, East 75.64' Top Center R/W
 Marker, S75E 133.46' 8" Tamarack, North 2641.74' Sec. Corner, South 2629.74' Sec. Corner

(A-5) From Chippewa County LCRC, L.2, P.253 (1960 Survey): 1" Iron pin in monument box.
 From MDOT Notes, 4-26-91: 1" pin witnessed prior to road construction.

1992: Neil Hill found and accepted 1" pin (L.7, P.357). N40W 79.94' Power Pole, S75E
 74.60' Guy Pole, S60W 84.88' Power Pole, S50E 116.11' 13" Elm, South 2641.74' $\frac{1}{4}$ Corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A-6) Found corner and accessories as recorded in Liber 7, Page 357 of the Chippewa
 County Records. Accepted corner position as found.

(A-5) Found corner and accessories as recorded in Liber 7, Page 357 of the Chippewa
 County Records. Accepted corner position as found.

**SURVEY &
 REMONUMENTATION**

JUL 26 1994

COMMISSION



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A-6) $\frac{1}{2}$ " iron rod & cap #27447
in monument box

WITNESSES

N 70 W 72.82' Power Pole
 West 75.67' Corner Fence Post
 S 65 W 106.43' Southerly Gate Post
 East 75.64' Top Center R/W Marker
 S 75 E 133.46' 8" Tamarack
 North 2641.74' Section Corner
 South 2629.74' Section Corner

(A-5) 1" pin in monument box at M-48
East and M-129

WITNESSES

N 40 W 79.94' Power Pole
 S 75 E 74.60' Guy Pole
 S 60 W 84.88' Power Pole
 S 50 E 116.11' 13" Elm
 South 2641.74' $\frac{1}{4}$ Corner

Signed by Keith R. WatersDate 7-22-94Surveyor's Michigan License No. 33142

**NOTE: Bearings are compass bearings corrected for declination.
 Distances are to a nail in side of witness objects unless noted.**

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
 REVISED MAY 14, 1975
 REVISED JAN., 1983