

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
Chippewa County Remonumentation Corner

For corners in

Chippewa County

Located in:

Corner Code #

1. Public Land Survey

T44N R1W L-9

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Sec.

S T R
S T R

4. Lot No.

, Recorded Plat

5. Private Claims

SECTION

BOOK 11 PAGE 210

\$7.00 LAND CORNER

\$2.00 MSSR

2 FEB 2001 3:59:07 PM Receipt #1103
RECEIVED FOR RECORD

CHIPPewa COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Keith R. Waters, in a field survey on November 28, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L-9 1/4 Corner Common to Sections 24 & 25, T44N, R1W.

1845 - Original corner established by James H. Mullett.

Witnesses: Cedar 10, N59°E 18 links - Hemlock 10, S47°W 16 links.

1908 - Chippewa County Surveyor Frederick H. Brown, RLS 944. Notes for Section 25 indicate, "corner gone - burning."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being reestablished as part of the Chippewa County Remonumentation Program.

Found no evidence of the corner. Reestablished corner by single proportionate measurement on line between the section corner at K-9 to the west and the section corner on the meridian at M-9 to the east. Reestablished corner falls 3.5'± south of the centerline of Highway M-48, on a fence line to the south, 1'± east of a fence line to the north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a 3/4" x 24" rebar with a plastic Chippewa County Remonumentation cap in a monument box at the corner location, which falls 3.5'± south of the centerline of Highway M-48, on a fence line to the south, 1'± east of a fence line to the north.

Witnesses:

Nail and plastic witness tag #33142 in 8" Spruce, N19°E 83.09'

Nail and plastic witness tag #33142 in 6" Spruce, N67°E 107.29'

Nail and plastic witness tag #33142 in 8" Tamarack, S54°E 79.10'

Nail and plastic witness tag #33142 in Power Pole (PD3/28), S14°W 78.42'

1/2" Iron in north shoulder of M-48, N02°W 19.49'

Signed by

Keith R. Waters

Date

12-29-00

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

T44N R1W L-9

BOOK 11 PAGE 210

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

