APR 0 7 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Chippewa County Remonumentation Corner

SECTION For corners in

Chippewa County Located in: Corner Code # 1. Public Land Survey T45N R2W C-5 Ţ R R T R Т 2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S

\$7,00 LAND CORNER \$2.00 MSSR

6 Mar 1998 1:33:16 PM Receipt #6451 RECEIVED FOR RECORD

CHIPPENA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 10 PAGE 167

20

2 3 ۷

5

6

7

9

10

12 13 Register of Deeds Stamp & File Number

Lot No.

, Recorded Plat

5. Private Claims

I, Keith R. Waters, in a field survey on November 11, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-5 Corner common to Sections 7, 8, 17, & 18, Town 45 North, Range 2 West

1849 - Original corner (sugar maple post) was established by Harvey Mellen, D.S. Witnesses: Hemlock 24, S40°E 35 links - Yellow Birch 18, N46°W 44 links

SVIMEY. 1906 - Chippewa County Surveyor Frederick H. Brown notes for Section 8 indicate an original corner here. Witnesses: Hemlock 20, S43½°W 52' - Sugar 18, N46½°E 84' - Hemlock 24, S36½°E 41'

1916 - County Surveyor Brown notes for Section 17 again indicate an original corner and monument. Both the 1906 and 1916 notes show a distance to section corner E-5 to the east of 5243 feet.

1939 - County Surveyor corner tie book indicates a 24" cement post and old saw at corner location. The above mentioned 24" hemlock and 18" sugar are noted to be there but broken off, hemlock dead. New witnesses: 12" Maple, S83°W 811/2' - 24" Sugar, S73°E 1381/2'

1982 - LCRC, liber 5, page 222, William L. Karr, P.S. 27450. Reset corner from local evidence, set 1/2" iron w/cap. Witnesses: 12"Maple, S41°E 66.39' - 8" Maple, S65°W 43.79' - 14" Triple Birch, N37°W 109.25' - Corner Fence Post, Due West 39'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County Remonumentation Program. Found a 1/2" iron (cap has been removed), two bearing trees and the stump of another, and the rotted corner fence post as called for in 1982 LCRC. The distance to section corner E-5 to the east is within 3 feet of above mentioned County Surveyor records. Accepted the corner as found and placed a plastic cap #33142 on the found iron.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found a 1/2" iron in the approximate centerline of Tilson Road at the corner location, placed a plastic cap #33142 on the found iron. Corner falls on the extension of an old fence line to the west. Witnesses:

16" Triple Yellow Birch, N37°W 109.12'

9" Maple, S65°W 43.68'

8" Maple, N80°W 29.30'

8" Maple, S39°E 65.64'

Note: Distances are to a nail/tag #33142 in the side of the tree. Bearings are compass bearings corrected for declination.

Keith R. Wate

Date 12-30-97

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

200K 10 PAGE 16

TE OF MICHIGAN

KEITH R.

WATERS

PROFESSIONAL SURVEYOR

No.

REVISED JAN., 1983 REVISED OCT., 1995

3314 POFESSIONAL

Surveyor's Michigan License No. 33142