LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 Chippewa County Remonumentation Corner

For corners in

Chippewa	Located In:	Corner Code #	\$7.00 LAND CORNER \$2.00 MSSR 21 JAN 1999 10:13:00 AH Receipt #13120 RECEIVED FOR RECORD CHIPPEWA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS  BOOK 10 PAGE 333 Register of Deeds Stamp & File Number
1. Public Land Survey	T <u>46N</u> R <u>2E</u> T R T R T R	F/G-3 # 나	
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S T R S S T R S T R R S T R R R S T R R R S T R R R T R R R T R R T R R T R R T R R T R R T R R T R R T R R T	<b>1</b> 4 · · · · · · · · · · · · · · · · · · ·	
4. Lot No, Rec	orded Plat		1 <sup>A</sup> B C D E F G H   J K L M

I, Larry R. Rogers in a field survey on October 15, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: (F/G-3) Meander Corner between Sections 4 and 9, Township 46 North, Range 2 East. The original corner was placed in 1845 by James H. Mullett, 15 chains (990 feet) East of 1/4 Corner. Corner fell in diperiments with no witnesses available. County Surveyor records make no specific reference to corner.

SAMELY SERVICE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F/G-3) Meander Corner between Sections 4 and 9, Township 46 North, Range 2 East.

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found no evidence of original corner position. Re-established corner position on the extension of a line from the Southwest original corner.

4 through the South 1/4 Corner of Section 4 at record G.L.O. distance East of 1/4 corner. Corner falls in very swampy area of tag alder and willow brush and is 28 feet South of remains of an East - West fenceline-origin unknown. Placed a steel fence post and four 3/4" x 18" steel pipes for witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (F/G-3) Meander Corner between Sections 4 and 9, Township 46 North, Range 2 East. Corner is a 3/4" x 48" 6" above grade with stamped aluminum Remonumentation cap.

Witnesses: Steel Fence Post North 2.0 feet 3/4" Witness Pipe N56"E 13.14 feet 3/4" Witness Pipe N47°W 19.28 feet S46\*W 3/4" Witness Pipe 13.51 feet 3/4" Witness Pipe S76°E 13.97 feet

30 DEC 1998 Signed by Date

OF MICHIGA LARRY R. ROGERS and Surveyor NO. 28251 AND

Surveyor's Michigan License No. 29251

All bearings are compass bearings corrected for declination (6°W). All distances are to a nail and tag in the side of witness object unless otherwise noted.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971