

MAR 1 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970  
Chippewa County Remonumentation Corner

For corners in

Chippewa Located In: Corner Code #

1. Public Land Survey	SAME CORNER	T 47N R 1E	M-11/12
		T 47N R 2E	A-11/12 ✓
		T	R
		T	R
2. Property Controlling in Section	S	T	R
	S	T	R
3. Miscellaneous Property in Sec.	S	T	R
	S	T	R

#2

\$7.00 LAND CORNER  
\$2.00 MSSR  
21 JAN 1999 10:33:17 AM Receipt #13123  
RECEIVED FOR RECORD  
CHIPPEWA COUNTY - STATE OF MICHIGAN  
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 10 PAGE 358  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Larry R. Rogers, in a field survey on December 02, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:  
(M-11/12) Meander Corner on East Line of Section 36, Township 47 North, Range 1 East.  
The original corner was placed in 1845 by John Mullett, 20 chains South of Section Corner. The Oak Point Plat, recorded in 1958, show a concrete monument on the South line of Outlot "C" and on the "Section Line".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
(M-11/12) Meander Corner on East Line of Section 36, Township 47 North, Range 1 East.  
This corner is being perpetuated as part of the Chippewa County Remonumentation Program.  
Found no evidence of original Corner position. The concrete monument on the South line of Outlot "C" was recovered, but since this monument is 704 feet farther South than the position of the original Meander Corner it was deemed inappropriate to use as the Meander Corner. The Point of Beginning (Northeast corner of Section 36) as shown on Oak Point Plat is actually the Witness Corner 33 feet South of the Section Corner. If the Meander Corner were to be re-established at record distance (1320 feet) South of the Section Corner it would fall somewhere near the middle of Lot 13 of said Oak Point Plat. Since the Meander Corner has little, if any, impact upon adjacent property lines, we decided to utilize a found plat monument at the intersection of the East line of Section 36 with the North line of Lot 12 of Oak Point Plat as the Witness Corner to the Meander Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
(M-11/12) Meander Corner on East Line of Section 36, Township 47 North, Range 1 East.  
Corner is a concrete plat monument at the intersection of the East line of Section 36 with the North lines of Lot 12 of Oak Point Plat, 1118.95 feet South of Northeast corner of Section 36.

Witnesses:  
14" Double Maple S78°W 11.74 feet  
14" Maple N03°E 17.81 feet  
6" Maple S57°E 19.70 feet  
4" Maple S08°E 14.17 feet

Signed by \_\_\_\_\_ Date 30 DEC 1998

Surveyor's Michigan License No. 29251

NOTE: All bearings are compass bearings corrected for declination (6°W). All distances are to a nail and tag in the side of witness object unless otherwise noted.

