

MAR 18 1999

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
Chippewa County Remonumentation Corner

SECTION

For corners in

Chippewa

Located In:

Corner Code #

1. Public Land Survey SAME CORNER { T 46N R 2E
T 47N R 2E
T R
T R
S T R
S T R
S T R
S T R
2. Property Controlling In Section
3. Miscellaneous Property in Sec.

A/B-1
A/B-13 ✓

#3

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Larry R. Rogers in a field survey on November 5, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

\$7.00 LAND CORNER

\$2.00 HSSR

21 JAN 1999 10:34:05 AM Receipt #1312

RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 10 PAGE 359

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1	6	5	4	3	2	1						
2												
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

(A/B-1) Meander Corner on North line of Section 6, Township 46 North, Range 2 East.

Original corner post was placed in October 1845 by John Mullett. Corner shown in 1933 subdivision of "Plat of Hiawatha Grounds" as a 1" iron in concrete. Corner was referred to in 1975 survey by N.D. Alix as a found iron pipe (Job #: 74040-S). In 1991, Larry Weinreis, P.S. 32343, found a concrete monument with 1/2" iron pin and filed a L.C.R.C. in Liber 7, Page 321 of the Chippewa County corner records. Weinreis corner has been used in several surveys since 1991.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A/B-1) Meander Corner on North line of Section 6, Township 46 North, Range 2 East.

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found no evidence of original corner position. Found 1/2" iron pin in concrete monument as recorded by Weinreis. Unable to find pipe referred to in Alix survey. Corner works well with other monumentation from "Plat of Hiawatha Grounds". Accepted corner position as found and witnessed. Corner is 8 feet North of centerline of East - West two track road. Distance East to 1/4 Corner is 1444.80 (1462.56 G.L.O.)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A/B - 1 Witness Corner to Meander Corner on North line of Section 6, Township 46 North, Range 2 East.

Corner is a concrete monument with 1/2" iron pin, 28 feet East of water's edge of the St. Mary's River. Concrete around top of monument has been destroyed.

Witnesses:

Concrete Monument	North	32.90 feet
10" Ash	N53°E	47.85 feet
5" Ash	S62°E	48.19 feet
14" Ash	S03°E	48.68 feet

Signed by _____

Date 30 Dec 1998

Surveyor's Michigan License No. 29251

NOTE: All bearings are compass bearings corrected for declination (6°W). All distances are to a nail and tag in the side of witness object unless otherwise noted.

