

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970 as Amended**

For corners in

<u>Chippewa</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S <u>33</u> T <u>50N</u> R <u>6W</u>	<u>5</u>
	S <u>33</u> T <u>50N</u> R <u>6W</u>	<u>1/64 E. of 5</u>
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Jun 05 2007

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 20\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

(5-Sec. 33) North 1/16 corner, Section 33. Not established in the original survey.  
 (1/64 E. of #5) C-W-NE 1/64 corner, being the SE corner of the SW1/4 of the NW1/4 of the NE1/4 of Section 33. Not established in the original survey.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

(5-Sec. 33) Established the corner midway and on a straight line between Quarter corner 1316.39' north and the intersection of 1/4 lines of Section 33 1316.39' south. From the position thus established, I found an "angle" iron, placed by persons unknown N80W 17.3' distant which I did not accept as marking the position of the corner.  
 (1/64 E/ of #5) Established the corner midway and on a straight line between 1/16 corner numbers 5 and 6, 660.09' west and east. The corner lies on the east side of a NE-SW trail.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

(5) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Set measuring nails in:	(1/64) Set 1"IDx36" I.pipe with plastic cap stamped MICH DNR PS33986". Set measuring nails in:
6" J.Pine S77W 19.12' mrkd "N1/16 BT"	10" J.Pine S21E 4.85' mrkd "1/64 BT"
11" J.Pine N28W 13.64' do	5" J.Pine N57W 23.0' do
5" R.Pine N30W 33.7' do	12" J.Pine N10W 42.82' do
7" R.Pine S55E 13.82' do	8" J.Pine N71E 35.22' do
Bearings are magnetic. Distances are to nail with tag.	Bearings are magnetic. Distances are to nail with MDNR tag.



Signed by Stephan J. Szyszkoski  
 Surveyor's Michigan License No. 33986

Date 6/28/07

For the Michigan Department of Natural Resources, Office of Land and Facilities