

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson (County)
Located In:
Corner Code #
L01
Public Land Survey
Property Controlling Section
Miscellaneous Property in Sec.
Lot No.
Private Claims

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 in a grid pattern.

Jeremy J. Pipp, in a field survey on 6/17/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
in this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(L01) North Quarter corner Section 1 (not a common quarter corner; correction line). Not
set as part of Original Survey but the following surveys should be noted. 1846: William
Burt, DS. established 4th correction line (South township line of T41N-R28W). 1848: James
Mullett, D.S. Set NE Township Corner (T40N-R29W) on the 4th correction line; notes
distance of 17.50 Chains (1155') to Section corner common to Sections 32 & 33 (T41N-R28W).
1849: James Mullett, D.S. Set post on 4th correction line for section corner common to
Sections 1 & 2 (T40N-R29W); notes distance of 19.58 Chains (1292.28') to Section corner
common to Sections 31 & 32 (T41N-R28W).

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L01) Corner position established by single proportionate measurement on the 4th
correction line between the South One-Quarter corner of Section 32 and Southeast corner of
Section 32 (both of T41N-R28W) using the distances noted in the 1846 (4th correction
line), 1848 (East Township line T40N-R29W), and 1849 (Interior Section lines T40N-R29W)
Original Notes and Township Plats. Proportion was performed using existing monuments
marking SE, S 1/4, and SW Corners of Section 32 T41N-R28W AND NE and NW corners of Section
1 T40N-R29W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L01) DNR monument
5" Poplar N09E 6.47' (1/4S,BT)
6" Spruce S86E 58.74' (1/4S,BT)
5" Poplar S04E 12.15' (1/4S,BT)
5" Poplar N71W 19.05' (1/4S,BT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by [Signature]
Surveyor's Michigan License No. 50447
Date July 15, 2014

