 	_	~	r	57	Ε	n
مدد	1	U	1.	IJ	L.	U

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 1973 DEC 14 112: 24

For corners in			
Dickinso	Dn Located In: Corner Code #		negeter of CTDS
(Cou	unty)		REGISTER OF CLEDS
City of	Kingsford 7 40Ng 31W H-11		SURVEY &
1. Public Land	T R H-13		REMONUMENTATION
	TR		I TTIAICH ACHAINE SAN ICAN
	TR		ADD A O ADD
2. Property Co	ontrolling S TR		APR 02 1999
in Section	S TR		
3. Miscellane	ous STR		Register of Deeds Stamp & File Number
Property in	Sec. STR		Register of Deeds Stamp & File North Der
	Departed Plat		A B C D E F G H I J K L M
4. Lot No	, Recorded Plat		
5. Private Cia	11115		2 6 - 5 - 4 3 2 1 - 1
			3
	Aug. 20 10 98 do here	hy state that '	under 4 7 8 9 10 11 12
Robert I	F. Perkins, in a field survey on <u>Aug. 20, 19 98</u> do herel P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and	d 2 above w	ere in 5
requirements of	P.A. 74, Michigan P.A. of 1970, the corner points memorial in the current manual of survey the regulations and rules therefore as required in the current manual of survey the regulations and rules therefore as required in the current of by a decree of a Co	instructions	of the
United States Di	th regulations and rules therefore as required in the current mandards are the enterior, Bureau of Land Management or by a decree of a Copportment of the interior, Bureau of Land Management or by a decree of a Copportment of the interior.	ourt of Law a les of the Mic	and /or 6 18 17 10 13 13 13 13 13 13 13 13 13 13 13 13 13
that the corner	epartment of the Interior, Bureau of Land Management or by a decree of a co- points mentioned in lines 3, 4 and 5 above were in conformance with the rul Surveyors or by a Decree of a Court of Law; established, re-establish	ied, monum	ented, 7
Board of Land	d as expressed below:		8 -19 -20 -21 -22 -23 -24
		4	9
NOTE: Not r	more than 2 corners, all in the same town and range, may be recorded		10 30 29 28 27 26 25
on th	nis certificate.		11
			12 31 32 33 34 35 36
			13
A. Description	on of original monument and accessories and/or subsequent resto	ration:	2, 41, 21
	Corner Common to Sections 27	11 1 9 C	outh & Corner Section 34
H-11	34	P	ost by James H. Mullett, D.S. 1846
	Post by James H. Mullett, D.S. 1850	0	riginal Bearing Trees
	Original Rearing Tree	A	spen 3" N43°W 12 Lk. Sirch 4" N52°E 8 Lk.
	Spruce Pine 6" S44°E 88 Lk.	В	irch 4" NOZ E O BR.
	-F		
	No Evidence of Original Corner or Accessories Found. Found 3/4" Iron Pipe with 1" Square Punched Top (Ford Motor Co. Circa 1920) 1' N.W. of Fence Corner.	H-13 N	hing corner: No Evidence of Original Corner or Accessories Found. Found 4½" x 3½" Concrete Monument with 3/8" Iron Pin and 2 Bearing Trees. Corner accepted and used on numerous Surveys including Kingsford Hydro Plant to West and Ford Airport to North over past 60+ years.
H−11 Signed by	Accepted above described Pipe as Best Remaining Evidence of Corner Location. Replaced Same with 3½" Stamped D.C. Remon. Corner. New Witnesses Cherry 4" N28°W(M.B.) 23.88' Nail/Tag Cherry 8" S25°W(M.B.) 44.98' Nail/Tag R.Pine 18" N70°E(M.B.) 67.96' Nail/Tag 4" Steel Fence Post S40°E 1.0' 4" Steel Fence Post S40°E 1.0' 4" Steel Fence Post S88°W 8.535. Michigan Ligense Nep 12027 DICKINSON GORDET PERKINS SURVEY PEER GROUP AS THE OFFICALT GONNER UNDER MICHIGAN PUBLIC ACT No. 12027	H-13	Accepted above Concrete Monument as Best Remaining Evidence and Replaced same with 3½" Stamped D.C. Remon.Corner. New Witnesses W.Birch 10" S70°W(M.B.) 22.22' Ex. B.T. Maple 12" S48°W(M.B.) 12.91' Ex. B.T. Dbl. Map. 10" S48°W(M.B.) 44.41'Nail/Tag Spruce 7" N1°E(M.B.) 14.94' Nail/Tag Placed Carsonite Stake 0.55' West
	345 OF 1990 AT A MEETING HELD ON	JRIN APPROVI	ED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14.1975
	12-7-98 . WE COMMIST	1600	REVISED JAN., 1983
	Rolling I manufaction	" · · /	ber 2 Page 398 REVISED OCT., 1965
	COUNTY REPRESENTATIVE	_	7 7 10