## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in					
	-	-	ma	me	-fm

on this certificate.

Dickinson	Located In:	Corner Code #								
(County) West Branch Township 1. Public Land Survey	T 43N R 27W	E10								
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	T R S T R S 29 T 43N R 27W S T R S T R	7								
	corded Plat		<u>ا</u> ام	Regist	er of De	eds St	amp & I	File Nu	mber 'K	L M
ı, Jeremy J. Pipp , ii	8/23/201 n a field survey on 8/23/201		3	6-	-5		3-	1 2	+	
that under requirements of P.A.	74, Michigan P.A. of 1970, the corner regulations and rules therefore as requir	points mentioned in lines 1 and 2 red in the current manual of survey	,5				H	H		+
a Court of Law and /or that the c	Department of the Interior, Bureau of Lorner points mentioned in lines 3, 4 and	d 5 above were in conformance with	۳ <i>۱</i>	10-	- <u>1</u> 7	16-	15	11		-13-
the rules of the Michigan Board re-established, monumented, recov	d of Land Surveyors or by a Decree vered, found as expressed below:	of a Court of Law; established	9 -	19	20	2)	22	13	#	-24-
NOTE: Not more than 2 corr	ners, all in the same town and rang	e, may be recorded	10	90-	29	28-	27	1-26	#	25-

A. Description of original monument and accessories and/or subsequent restoration:
(E10) Quarter corner common to Sections 28 and 29. 1850: John Burt,DS. Set Post
witnessed by Spruce 10 N87W 28 links (18.48'), Cedar 8 S24E 19 links (12.54'). 1985:
Michigan DNR (David Babbitt PS#21558) Remonumented the corner at record bearing and
distance from the remains of an original bearing tree. Placed a DNR monument witnessed
by 6" Black Spruce S23W 9.3', 4" Balsam Fir N42E 2.1', 10" Tamarack N79E 43.5', 12"
Tamarack S88E 75.9'.

- (07) North One-Sixteenth corner common to Sections 28 and 29. Not set in original survey, no evidence of subsequent establishment.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (E10) Accepted found MDNR Monument and Four existing Witnesses (2 living [NE Tamarack, SW Spruce] & 2 dead). Left MDNR monument in place and rewitnessed (added nails & signs). Accepted found MDNR Monument and Witnesses as a careful and faithful PERPETUATION of the position of the original corner.
- (07) Corner position established mid-point and on-line between the East One-Quarter corner and the Northeast corner of Section 29.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E10) DNR monument	(07) DNR monument
Ex. 13"Tamarack N85E 43.61' (1/4S,NBT)  4" Ash S03E 36.58' (1/4S,NBT)  Ex. 9" Spruce S27W 9.53' (1/4S,NBT)  6" Maple N32W 44.50' (1/4S,NBT)	13" Cedar N06E 26.47' (1/16S,BT) 11" Cedar S89E 44.28' (1/16S,BT) 18" Tamarack S63W 12.10' (1/16S,BT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A carsonite rail was set North 1.5 feet.	9" White Birch N57W 19.13' (1/16S,BT) All trees are blazed, scribed, and parties. Ministerements are to nail in Side of tree, see rings are magnetic.
Signed by	JEREMY J.Date August 29, 2012

Surveyor's Michigan License No /// 50447

For the Michigan Department of Natural Resou

OCC. SURVEYOR FOR

STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

20133 20132

SCOLON AL