

**SURVEY &  
REMONUMENTATION**

**MAR 03 1998**

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

**RECORDED.**

For corners in

<u>Dickinson</u>	Located In:	Corner Code #
(County) West Branch Twp.		
1. Public Land Survey	T <u>43N</u> R <u>27W</u>	<u>C-11</u>
	T <u>    </u> R <u>    </u>	<u>    </u>
	T <u>    </u> R <u>    </u>	<u>    </u>
	T <u>    </u> R <u>    </u>	<u>    </u>
2. Property Controlling in Section	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
3. Miscellaneous Property in Sec.	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>

1997 NOV 13 AM 9:31

REGISTER OF DEEDS  
DICKINSON COUNTY  
IRON MOUNTAIN, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Ewart C. Muller, in a field survey on September 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Surveyed by John Burt, D.S. 1850

A. Description of original monument and accessories and/or subsequent restoration:

C-11 Set cedar post corner of Sections 29,30,31 & 32  
BT's: Hemlock 18 S63W 43 lks  
Hemlock 14 N71E 23 lks  
Original BT's destroyed during road construction.

ACCEPTED BY THE DICKINSON COUNTY  
SURVEY PEER GROUP AS THE OFFICIAL  
CORNER UNDER MICHIGAN PUBLIC ACT  
345 OF 1890 AT A MEETING HELD ON

11-12-97

ROP

COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-11 Found one inch iron pipe with plastic cap set by D. Babbit. He set corner by double proportionate measure using Section corner 2 miles east & 1 mile west & 1/4 corners 1/2 mile North & 1/2 mile south.  
Note: see corner report #406. Corner being replaced because of new road construction.  
NBT's: Balsam 8 N5E 59.5(Found.); Aspen 7 N29W 33.2 (Cut down)  
Balsam 9 S14W 53.7(Found.); Aspen 8 S20E 22.1(Cut down)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-11 Set 2 1/2" stamped D.C. Mon. in Mon. Box located 3.5 ft south of road centerline.  
NBT's: Balsam 9 N12E 60; Aspen 12 N66W 160.65; Balsam 11 S15W 54.13.  
Set 3 1/2" stamped D.C. Mon. for W.C. North 50'. set carsonite stake alongside witness corner.  
Note: Measurements to nails in side of trees. Bearings are Magnetic

Signed by Ewart C Muller  
Surveyor's Michigan License No. 15408

Date November 4, 1997

