

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

1998 DEC 14 PM 12:23

For corners in

Dickinson Located In: Corner Code #
(County)
Felch Twp.
1. Public Land Survey T43NR 28W D-11
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

REGISTER OF DEEDS
DICKINSON COUNTY
RON MORTIMER, 1998

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

SECTION

I, Robert F. Perkins, in a field survey on Sept. 3, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

D-11 $\frac{1}{4}$ Corner Common to Sections $\frac{29}{32}$
Post by John Burt, D.S. 1850
Original Bearing Trees
Y. Birch 14" S26°W 05 Lk.
W. Birch 26" N41°E 28 Lk.

ACCEPTED BY THE DICKINSON COUNTY
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT
346 OF 1990 AT A MEETING HELD ON
12-7-98

R.F.P.
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-11 1937 Wm. C. Johnson, C.E. Set 1" Iron Pipe and Marked W.Pine Bearing Tree.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-11 No Evidence of Original Corner or its Accessories Found.
Found 1" Iron Pipe and 22" W.Pine 1937 Bearing Tree referred to in "B" above.
Replaced 1" Iron Pipe with 3 $\frac{1}{4}$ " Stamped D.C. Remon. Corner.
New Witnesses:
Red Maple 9" N53°W(M.B.) 24.80'
Red Maple 7" N57°E(M.B.) 36.3'
Red Maple 10" S79°W(M.B.) 41.60'
W.Pine 22" N20°W(M.B.) 15.10' (1937 B.T.)

Signed by Robert F. Perkins
Surveyor's Michigan License No. 12027

Date Nov. 6, 1998

