LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #										
(County) FELCH TOWNSHIP 1. Public Land Survey	T 43N R 29W T 43N R 29W	E11										
Property Controlling Section Miscellaneous	T R S T R S T R S T R S T R S T R											
Property in Sec.	S			Regi	ster of	Deed	s Sta	& am	File (Numi	ber	
4. Lot No, Rec 5. Private Claims	corded Plat		1 A	В	C D		F G		I		C L	М
	2/27/20	013AD	2	— ხ	╬-	+-	4-	— ļ-	+	2	 -	_
, Jeremy J. Pipp , in that under requirements of P.A. 7	74, Michigan P.A. of 1970, the corner		- 4 1		- 8-	+	9	-10-	+	11	-12	_
above were in conformance with regulations and rules therefore as required in the current manual of survenstructions of the United States Department of the Interior, Bureau of Land Management or by a decree of						-	6	— —15-	‡	14	-13-	
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established re-established, monumented, recovered, found as expressed below:					20	+	21-	22_	F	23	24-	_
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.							33	-27- -34-		26— 35—	-25 -36	

A. Description of original monument and accessories and/or subsequent restoration:

(E11) Section corner common to Sections 28, 29, 32, and 33. 1848: Harvey Mellen, DS. Set Cedar post witnessed by: Cedar 14 S60E 9 links (5.94'), Cedar 18 N13W 13 links (8.58'); 1959: Michigan DNR (Billy Buckler PS#8887) Set 1" Pipe with 4"aluminum cap witnessed by 7" Cedar N42E 46 links (30.36'), 12" Cedar S44W 23 1/2 links (15.51').

(G10) Quarter corner common to Sections 27 and 28. 1848: Harvey Mellen, DS. Spruce post witnessed by: Y. Birch 16 S30E 12 links (7.92'); Hemlock 9 S60W 17 links (11.22'); 1980: Michigan DNR (Arthur Enger PS#13581) Set 1" Pipe with 3 3/4"aluminum cap witnessed by Sugar Maple 6 S02E 6.9', Sugar Maple 5 N77W 9.3', Sugar Maple 6 N62E 7.81.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E11) Accepted found MDNR Monument and one existing witnesses as a careful and faithful REESTABLISHMENT of the position of the original corner.

(G10) Accepted found MDNR Monument and Three existing witnesses as a careful and faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E11) DNR	monument	(G10) DNR monument							
EX 12" Cedar	N44E 30.45' (\$28,NBT)	EX 7" Maple N65E 8.09' (1/4S,NBT)							
11" Cedar	S83E 37.57' (S33,NBT)	EX 6" Maple S01E 7.00' (1/4S,NBT)							
11" Cedar	\$46W 31.88' (\$32,NBT)	EX 7" Maple N77W 9.50' (1/4S,NBT)							
10" Cedar	N86W 45.62' (S29,NBT)	12" Basswood NO1W 7.71' (1/4S,NBT)							
All trees are blazed, scribed, and All trees are blazed, scribed, and									
painted. Measur	rements are to nail in	painted beasurements are to nail in							
	earings are magnetic. A	side of the Appearings are magnetic. A							
Carsonite rail v	was set North 1.5 feet. /-	earsonite rail was set North 1.5 feet.							
Signed by	(Jerenny (with	July 22, 2013							

Surveyor's Michigan License No.

PIPF ST SERVIEY DIRISION

PERRION

TATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975

20193

20192

Revised Jan., 1983 Rervised Oct., 1995