

# SURVEY & REMONUMENTATION

MAR 13 2000

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN  
EMMET COUNTY  
RECORDED

99 DEC 28 AM 9:36

For corners in **SECTION**

*Glenn A. Liger*  
REGISTER OF DEEDS

EMMET Located In: READMOND TOWNSHIP Corner Code #  
(County)

1. Public Land Survey T 37N R 6W CD-3 MC  
ECRP #202

2. Property Controlling S      T      R      #6  
in Section S      T      R       
3. Miscellaneous S      T      R       
Property in Sec. S      T      R     

4. Lot No.         , Recorded Plat         

5. Private Claims         

I, Richard E. Oelke, in a field survey on 10 December, 19 99 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

**Abstract:** GLO set corner in 1840's. Robinson set or found something in 1926. Bidstrup, found rotted post and replaced it with a concrete monument and was subsequently replaced with a 5/8" rod from existing accessories. It has been used in subsequent surveys by local surveyors.

See back page for chronological history of corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

**Found:** 5/8" iron rod set by Bidstrup. RHWL +/- 39'W. Existing water +/-136' W.

2) S 68° E, 12.13', 12" cedar, nail in S. face  
3) S 02° W, 13.80', 5" cedar, nail in E face

N 90°E, 5.58', 12" w. birch, tagged 24626 in S face

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**Set:** The 5/8" rod noted above was removed, and replaced with a 2" diameter, 30" long, PVC pipe with a base magnet and a standard brass Emmet County Survey Remonumentation Program Cap. This position is accepted as a careful and faithful perpetuation of the position of the original corner.

### Additional New Witnesses:

N 51° E, 21.18', 8" cedar tagged 33983 in NW face  
N 87° E, 21.70', 12" red pine, tagged 33983, in SE face  
S 28° E, 19.75', 8' cedar, tagged 33983 in N face  
East, +/-2', carsonite marker

APPROVED LAND CORNER  
P.A. 345 OF 1990  
Emmet County  
*RE. OELKE*  
ECRP Rep. 12-23-99



Signed by *R.E. Oelke* Date 10 December 1999

Surveyor's Michigan License No. 33983

SURVEY &  
REMONUMENTATION

MAR 13 2000

SECTION

LIDER A  
PAGE 318

EMMET COUNTY REMONUMENTATION PROGRAM  
CORNER NO. 202

37-6-MC

T37N R6W meander corner bet. Secs. 5 & 8  
west end of DIVISION RD. extended

Date	Surveyor	Found	Witnesses	Notes
1840	GLO	set post	1) S 6°W 7L 10" Cedar 2) N 50°E 7L 6" Black oak	
1928	Robinson	shows corner symbol		
1970	Bidstrup	fd. Top of 4" squared stake on ground, dug and fd. remains of bottom of stake, replace with concrete monument	1) N 5°E, 35.15', 2) S 65°E, 12.14', 3) S 2°E, 13.65',	nail in 3" Balsam nail in 12" cedar nail in 5" cedar
1990	Young	monument missing, replaced with 5/8" rebar from above witnesses		
1990	Green	shows symbol		
1993	Young	fd 5/8" rebar		