

MAY 31 2000

## Remonumentation corner under P.A. 345, Michigan P.A. of 1990

C	153 153 153	C	JE 1	É	١	N
- 7			₩.	4 -2	77	, ,

## LAND CORNER RECORDATION CERTIFICATE

		Filing Requi	rement of Act 74, Mich. P	P.A. 1970	
For	corners in			DEED 256	9 pine 122
	Genesee	Located In:	Corner Code ##	LIBER 400 U	
	(County)	Fenton Town	ishin	02 F83	
		TENON TOWN	- 1	7 (3) Second	RECORDE
1.	Public Land Survey			T (O	i i i
		<u>T</u> R	· •		# # # # # # # # # # # # # # # # # # #
		TR		36	
		R		The state of the s	and the same of th
2.	Property Controlling	S R		AGA	
	in Section	S T R		- 10°	
3.	Miscellaneous	S		Register of Deeds	Stamp & File Number
	Property in Sec.	S T R			a
				9.00 Filed	affled
4.	Lot No , R	ecorded Plat		• • •	) EFGHIJKL
5.	Private Claims				
				2 6 5	
		5. le		3	
	* ** ** ***			4 - 7 - 8	9-10-11-12
١,	James E. Kovas, PS, P		tember 27 , 19 <u>94</u>	, , ,	
		uirements of P.A. 74, Michigan P.		VI -19 I 17	16 15 14 13
		<ul> <li>conformance with regulations a actions of the United States Dep</li> </ul>	•	_1 1 1	
		Court of Law and/or that the cor			
	•	h the rules of the Michigan Board	•	e of a	21 22 23 24
		e-established, monumented, re			
exp	ressed below:			10 30 29	28 27 26 25
NO.	TE: Not more than 4 co	orners, all in the same town	and range, may be recorded	17 -	<del></del>
	on this certificate.		• , ,	12 _3132	- 33
	•			13	
Α,	Description of original r	nonument and accessories a	nd/or subsequent restoration	n:	
	,	S, set post, two accessories	•		
		ument description, County Sur	veyor Post	Ratified by	Peer Group in
	Witness Book, two ac			ranner vy	ith P.A. 345, 1990
		Found pipe crock, Genesee Cour	nty Witness	SCCOLDSLICE AN	INI F.A. SASA
	Book, cor. No. 85, cig	ht accessories ' Iron, L.C.R.C., D.L. 2309 P. 336	Line I D	Co. Rep.	of Carlson
	Phillips, RLS #19002		, Haron K.	Or ush Fir	A COL
	1988/RODeeds - Found "T	"Iron, Recorded survey D.L. 2	830 P. 834,	Date (9 📿	- LE3 163C) VI
		S #32332, four accessories	,		/· 1
		Iron, Unrecorded Survey by	Cornerstone		
	Surveying, G. Bonno, L.S.	#32332, four accessories			
B.	Description of corner e	vidence found and/or method	applied in restoring or reest	tablishing corner:	
	1994/REMON. SUMMARY OF EXISTING ACCESSORIES:			MEASURED	
		Iron, Wade-Trim, Inc. Remonum			
		- S45E 64.1' 12" Oak (now 18			
		4.6' 10" Oak (now 24") 19.7' 2" Spruce (now 20")	(measured to cer (measured to cer		
		37.76' Gould washer in 12" Pine	•	67.80°	
		29.80' Spk./w #22445 twin 10" I		29.75′	
		3.35' Gould washer 10" Hickor		23.44'	
	South 5	0.30' "T" Iron at NW corner of		50.40'	
		50.39′ 1/4″ Re-rod		50.40'	
		0.71' 12" Oak (now 15")	(measured to na	<u>.</u>	
		4" Shagbark Hickory (now 6")	(measured to na	0-	
	M10M 2	8.81 12" Norway Spruce	(measured to na	il/tag) 29.75'	

Ratified by Genesee County Peer Group October 25, 1994


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

## ACCESSORIES:

1994 Remon. Found "T" Iron, Wade-Trim, Inc. Remonumentation)
N70E 67.80' Gould washer in 14" Pine
N30W 29.75' Spk/w #22445 twin 12" Pine
S45E 40.80' Nail/tag in 15" Oak
S20W 23.44' Gould washer 14" Hickory

I set the with br





e standard 30" X 2 3/8" Berntsen stainless steel tube ass remonumentation cap over the "T" Iron.	U

Signed by	E. Kore	Date12/6/94	
Surveyor's Michigan License No.	3313B	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28 REVISED MAY 14 REVISED JAN.	1, 1975