

MAR 02 2000

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in **SECTION**
Gogebic

Located In:

Corner Code #

(County)

Section 20 44N 39W C-9

1. Public Land Survey

T	R	
T	R	
T	R	
T	R	
S	T	R
S	T	R
S	T	R
S	T	R

2. Property Controlling in Section

3. Miscellaneous Property in Sec.

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

~~Monument~~ corner common to sections 19, 20, 29, 30, T44N, R39W

I, John R. Garske in a field survey on January 5, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2			
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

Original survey by Wells Burt, D.S. in 1851.

Original Bearing Trees: 12" yellow birch S46°E 17 links

8" yellow birch N31°W 21 links

Corner restored in 1956 by U.S. Forest Service.

1961-Donald Lappala, RLS #12585 found 3" x 66" cedar post set by U.S. Forest Service, and replaced the corner with 2" x 5' long galvanized iron pipe, with a 3" brass cap stamped to identify the corner from which he established:

8" sugar maple N29°E 28 links

6" sugar maple S36° 30' W 19 links

8" sugar maple N49° 30' W 38 links (corner recorded liber 1, page #5)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found the monument and accessories as described above, all in good condition. I set nails in all the trees and recorded new ties as noted below with new B.T.'s established.

(Research on file)

DEER CROUP APPROVED
Richard D. Dahn 7/20/99
COUNTY CLERK

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Monument found as described above from which I established the following witnesses:

Wood post	N87°W	3.70 feet (new)
10" maple	S85°W	12.97 feet (new)
12" maple	N33°E	18.30 feet (existing) (18.48')
12" maple	S10°E	4.92 feet (new)
12" maple	N49°W	25.2 feet (existing) (25.08')
Steel sign rail	East	2.0 (new)

Signed by

Surveyor's Michigan License No.

Date

7-20-99

