

# LAND CORNER RECORDATION CERTIFICATE

## Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office } ss.  
Gogebic County }

For corners in  
Gogebic  
(County)

Located In:

Corner Code ##

1. Public Land Survey

T 44N R 41W

E-F, 3b

T R

003

T R

003

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

RRV,

15/18/98

4. Lot No. , Recorded Plat

5. Private Claims

PEER GROUP

Approved

Richard L. Pisoni

4/7/94

I, Gary L. Pisoni, in a field survey on December 20, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original Corner established by Algernon Merryweather, U.S. Deputy Surveyor on July 7, 1852.

Original Corner: Wood Post

Original Bearing Trees:

Cedar	8"	S 50° E	28 links (18.48 feet)
Alder	4"	N 28° E	3 links (1.98 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original corner evidence found. Found a 5/8" dia. x 32" iron pin located on the East shore of Cisco Lake marking corner position. Iron pin set by unknown person. Iron pin has been used for lot surveys in Sections 4 and 9. I accept the iron pin as the best available evidence for restoring the corner position.

Placed iron pin inside of an aluminum monument.

Bottom B.T. blazes only and no. B.T. signs because corner is near cabin.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, I set a 2" diameter by 30" long split base aluminum pipe monument with a 3" cast aluminum cap, stamped to read: T44N, R41W, S-4, S-9, M.C., 1993, RLS- 27457 from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

White Pine	10"	S 27° E	15.69 feet
White Pine	9"	N 53° E	14.50 feet
White Pine	8"	N 05° W	15.34 feet
Steel Sign Post		West	1.07 feet

Signed by Gary L. Pisoni

Date 3-22-94

Surveyor's Michigan License No. 27457

U.S.F.S. #E-10,11

