

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Gogebic
 (County)

Located In:

Corner Code #

1. Public Land Survey

T 44N R 41W

G-3a, 4

T R

005

T R

T R

005

2. Property Controlling
 in Section

S T R

S T R

R&D

3. Miscellaneous
 Property in Sec.

S T R

S T R

10/18/98

Register's Office } ss.
 Gogebic County }

Received for record the

18th day of APRIL

A. D. 1994 at 1:20 o'clock

P. m., and recorded in

Liber 5 of CORNERS

on page 34

Betty Soar Deputy
 Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

PEER GROUP

Approved

5. Private Claims

Richard L. D. ...

4/7/94

I, Gary L. Pisoni, in a field survey on December 20, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original Corner established by Algernon Merryweather, U.S. Deputy Surveyor on July 3, 1852.

Original Corner: Wood post

Original bearing tree:

Birch 10" N 15° W 13 links (8.58 feet)

15.00 CHS. SOUTH

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original corner evidence found. Found a 1 3/4" x 3' iron pipe located on the North edge of the shoreline marking corner position. Iron pipe set by unknown person. Iron pipe has been in place since the 1960's and has been used for lot surveys in Sections 9 and 10. I accept the iron pipe as the best available evidence for restoring the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, I set a 3/4" outside diameter by 3 feet long aluminum rod monument with a 3" cast aluminum cap, stamped to read: T44N, R41W, S-9, S-10, M.C., 1993, R.L.S. 27457 from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

Balsam	4"	N 13° E	9.23 feet
Balsam	7"	S 63° E	10.15 feet
Balsam	6"	N 36° W	29.65 feet
Steel sign post		N 55° E	0.91 feet

Signed by

Gary L. Pisoni

Date

3-22-94

Surveyor's Michigan License No. 27457

U.S.F.S. #E, F-13

34

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

