

SURVEY & REMONUMENTATION

AUG 6 8 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office
Gogebic County

Received for record the

11TH day of JUNE

A. D. 1997 at 10:45 o'clock

A m., and recorded in

Lib. 6 of CORNERS

on page 151

Colleen M. Kichak, Deputy
Register of Deeds

Register of Deeds Stamp & File Number

For corners in

Gogebic

(County)

Located in:

Corner Code #

1. Public Land Survey

T 45N R 46 W

KL 3-4

T R

T R

T R

T R

2. Property Controlling

S T R

in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Mile Corner #5½, Mich.---Wisc. State Line

I, Richard L. Drahn, in a field survey on May 22, 19 97

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt in 1847. Original B.T.s --- Y. Birch 14" N.52 E. 5 links (3.30') --- Cedar 8" S.11 E. 16 links (10.56') ---

Corner restored in 1928 by Earl G. Harrington from the two original B.T.s. The B.T. at N.52E. was still alive and the B.T. at S.11 E. was dead and still scribed. He set a standard brass capped concrete monument and one new B.T.s: --- Y. Birch 10" S.30-15 W. 26.7 ft.

Research form on file with Gogebic County records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered the 1928 standard brass capped concrete monument as described in Harringtons notes. His 1928 B.T. is now a badly decayed 12-16" Y. Birch stump.

Only a shallow depression at S.11 E. remains from the Cedar B.T. and the Y. Birch B.T. at N.52 E. is now a very large Y. Birch stump decayed to well below ground line.

PEER GROUP APPROVED

Richard L. Drahn 6/10/97
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the above described concrete monument I established the following:

9"	Sugar Maple	N.04 E.	15.34 ft.
5"	Sugar Maple	S.42 E.	23.00 ft.
10"	Sugar Maple	S.42 W.	32.32 ft.
6'	Steel sign rail	N.25 E.	2.27 ft.



Signed by Richard L. Drahn

Date June 5, 1997

Surveyor's Michigan License No. 21564