

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 51N R 36W	E7
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 17 T 51N R 36W	16
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 16 09/02/2010 do hereby state

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E7) Corner common to Sections 16-17-20-21. 1959 - Corner remonumented by Billy D. Buckler RLS from local evidence. Set 1" pipe with 4" brass cap. 6" Sugar N25W 43.5 links, 8" Sugar S32E 34.5 links, 12" Sugar N45E 50 links, 12" Black Cherry S44W 22 links. 1993 - The undersigned recovered the 1959 monument disturbed and installed a new monument at the corner position, at record bearing and distance from the 1959 witnesses.

(16-Sec. 17) East 1/16 corner between Sections 17 and 20. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E7) Found the 1993 monument, a 1"IDx32" I.pipe with 4" alum. MDNR cap, date stamped 11/9/93, at record bearing and distance from the 1959 witnesses as follows: Sugar NW in good condition but a large tree between it and the corner reduces its utility, Sugar SE a stump with notch visible, Sugar NE in good condition, Black Cherry SW a standing dead stub. Accepted the monument as the best available evidence of the position of the corner.

(16-Sec. 17) Established the corner midway and on the Section line between Quarter corner 1321.03' west and Section corner 1321.03' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E7) Found 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
15" Sugar N50E 33.1' old blazes (1959 NBT)
12" Sugar S52E 27.3' mrkd "S21 NBT"
12" Sugar S09W 5.85' "S20 NBT"
4" Sugar S58W 14.45' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(16) Set 1"IDx32" I.pipe w/ 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
15" Sugar N04W 21.6' mrkd "1/16S BT"
7" Sugar S50E 12.75' do
11" Sugar S44W 16.25' do
6" Sugar N67W 30.75' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 01/06/2011

For the Michigan Department of Natural Resources and Environment, Forest Management Division

