

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 51N R 36W	E5 (GCDB 300500)
2. Property Controlling in Section	S T R	
3. Miscellaneous Property in Sec.	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 09/22/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner common to Sections 8-9-16-17. 1957 - Billy D. Buckler RLS found the corner monumented with a 2" iron pipe found at record bearing and distance from an original Hemlock BT S75W 25 links. Replaced the pipe with a 1"IDx36" iron pipe with 4" brass MI Dept. of Conservation cap. 9" W.Pine N55°W 96 links, 10" Hemlock S26°W 52 links, 15" Hemlock N74°E 52 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found the 1957 monument in good condition, projecting 3 ft. A.G., at record bearing and distance from the NBT Hemlock S26°W 52 links, in good condition with overgrown blazes. The two northerly 1957 NBTs would now fall in a power line clearing and they were not found. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 1"ID I.pipe with 4" brass MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:  
18" Hemlock S29°W 35.1' old blazes (1957 NBT)  
11" Maple S76°E 2.45' mrkd "S9 NBT"  
15" Hemlock S30°W 12.95' "S17 NBT"  
Power pole #130 (S'ly of three) N07°W 37.75' nail and tag in W'ly face.  
E= 7855776.615 N= 228354.473



Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
Coord. Ref.=NGS PID RL0593: N= 221669.506 m. E= 7868965.488 m.

Signed by Stephan J. Szyszkoski Date 03/12/2015  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division