

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 34 T 52N R 35W S _____ T _____ R _____ S _____ T _____ R _____	H12
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		6		5		4		3		2		1
5													
6	10		9		8		7		6		5		4
7													
8	13		12		11		10		9		8		7
9													
10	16		15		14		13		12		11		10
11													
12	19		18		17		16		15		14		13
13													

I, Stephan J. Szyszkoski, in a field survey on 01/24/2012 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(H12) Center of Section 34. 1982 - recorded by K.L.Sackett RLS: Found and restored corner position
at 1 1/2" ID iron pipe set by P.A. Larsen in 1925. 7" Y.Birch N61E 14.7', 7" Y.Birch N16W 12.8', 5"
Y.Birch S01W 17.1', 7" Maple, squared, South 1.3'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(H12) Found the 1 1/2" iron pipe of record, in good condition, projecting about 3" above ground, at
record bearing and distance from three of the 1982 witnesses. The BT Y.Birch N61E is standing dead.
The BT Y.Birch S01W is gone. The BT Y.Birch N16W and BT squared Maple are in good condition.
Accepted the monument as a careful and faithful determination of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(H12) Drove a 1" ID x 32" I. pipe with 4" alum. MDNR
cap into existing 1 1/2" dia. Iron pipe.
Set measuring nail with MDNR tag in the side of:
8" Y.Birch N13W 13.2' old blazes 1982 BT
13" sq'd Maple S55W 1.10' mrkd "C1/4 BT"
4" Y.Birch S77E 14.15' do
6" triple Sugar N69W 26.35' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 01/31/2012

For the Michigan Department of Natural Resources, Forest Resources Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971