

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton

(County)

Located In:

Corner Code #

1. Public Land Survey

T 52N R 35W

A2

T R

T R

S T R

2. Property Controlling
in Section

S 6

T 52N R 35W

4

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

Register of Deeds Stamp & File
Number

4. Lot No. , Recorded Plat

5. Private Claims

Jun 06 2007

I, Stephan J. Szyszkoski, in a field survey on _____, 20____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A2) Quarter corner on the West side of Section 6 T52N-R35W. 1845 - Established by Wm.A.Burt, Deputy Surveyor 40.00 chains north of A3 and 39.59 chains south of A1, according to the GLO field notes and the official GLO plat of T52N-R36W. The official GLO plat for T52N-R35W gives the distance between corners A2 and A1 as 39.39 chains. Wm.A.Burt set post and marked Sugar 12 S41E 22 links, Sugar 14 N80W 27 links. 1932 - M.C.Larson states that he found Sugar BT. No mention of monumentation.
(4-Sec. 6) Northwest 1/16 corner, Section 6. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A2) The original post and accessories were not recovered. Found the rotting stump remains of what initially was suspected to be the Sugar BT noted by Larson, no marks visible, but the stump was determined to be that of a Y.Birch and was therefore not accepted. Reestablished the corner on the Range line between corners A1 and A3 40 chains north of A3, and 39.39 chains south of A1, proportionate to the measurements given on the official GLO plat for T52N-R35W. Distance north and south to these corners were determined to be 2610.01' and 2650.42', respectively.
(4-Sec. 6) Established the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A2) Set 1"IDx32" I.pipe with 4" alum.
MDNR cap. Set measuring nails in:
10" Sugar N50E 54.4' mrkd "1/4S NBT"
7" Sugar S70E 36.4' do
17" Sugar S06E 10.1' do
8" Sugar N60W 5.3' do
Set sq'd spruce post adjacent. Bearings
are magnetic. Distances are to nail
with MDNR tag.

(4) Set 1"IDx32" I.pipe with 4" alum.
MDNR cap. Set measuring nails in:
7" Maple N60E 20.7' mrkd "1/16S BT"
8" Sugar S50E 3.25' do
3" dbl. Sugar S35W 2.6' do
13" Maple N60W 3.4' do
Set sq'd cedar post adjacent. Bearings
are magnetic. Distances are to nail
with MDNR tag.

Signed by

Stephan J. Szyszkoski

Date

7/12/07

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
Revised May 14, 1975
Revised Jan., 1983
Revised Oct., 1995