

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Houghton

(County)

Located In:

Corner Code #

1. Public Land Survey

T 52N R 35W

09

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Nov 28 1995

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 19\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

(09) Quarter corner common to Sections 20-29. Corner re-monumented in 1953 by Billy D. Buckler, at the original position, as determined from one original B.T. Buckler placed a 1" pipe with a 4" brass cap at the corner position and marked the following: 8" H. Maple S02W 59 links, 8" H. Maple N84E 52 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(09) Recovered the 1953 monument, a 1" I.D. iron pipe capped with a 4" dia. brass Michigan Dept. of Conservation tablet, in good condition. The 1953 witnesses were not recovered. Left the monument in place and marked four new witnesses as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(09) Found 1" pipe with 4" brass MI  
Dept. of Conservation tablet. Blazed  
and scribed the following:

10" Sugar S35W 24.9' "1/4S NBT"  
8" Sugar N57W 22.8' "1/4S NBT"  
12" Sugar S74E 22.5' "1/4S NBT"  
5" Sugar N52E 32.0' "1/4S NBT"

Bearings are magnetic.



Signed by

Stephan J. Szyszkoski

Date

3/13/97

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources - Forest Management Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN. 1983  
REVISED OCT., 1995