

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 52N R 36W	F5
	T R	(GCDB 340500)
	T R	
2. Property Controlling in Section	S 21 T 52N R 36W	14
	S T R	(GCDB 400320)
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 10/23/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(14-Sec. 21) South 1/16 corner between Sections 21 and 22. Not previously monumented.

(F5) Quarter corner common to Sections 9 and 16. 1846 - Established by Hiram and Sylvester Higgins,
Deputy Surveyors, on the Section line between Section corners 40.08 chains east and 40.09 chains
west. Set post. Sugar 10" N70°W 24 links, Hemlock 10" S55°E 26 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 21) Established the position for the corner midway and on the Section line between Quarter
corner 1401.51' north and Section corner 1401.51' south. The MCS83 grid bearing of the Section line
is N 05°35'50"E.

(F5) The original post and accessories were not recovered. Found no evidence of the position of the
original corner on the ground. Reestablished the position for the corner on the Section line
between Section corners 2650.43' west and 2649.76' east, proportionate to the original record.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
3" B.Spruce N15°W 13.8' mrkd "1/16S BT"
5" Maple S85°E 18.1' do
6" B.Spruce S31°E 27.5' do
8" B.Spruce S45°W 16.8' do
Set sq'd cedar post adjacent.
E= 7857647.185 N= 235286.932

(F5) Set 1"IDx28" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Y.Birch N01°W 23.15' mrkd "1/4S NBT"
8" Sugar S50°E 13.1' do
5" Maple S30°W 8.6' do
4" Sugar N70°W 1.65' do
Set sq'd cedar post adjacent.
E= 7856769.130 N= 238050.671

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=NGS PID RL0502: N= 234995.272 m. E= 7857774.766 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/18/2013

For the Michigan Department of Natural Resources, Forest Resources Division

