

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 52N R 36W	M11
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 25 T 52N R 36W	7
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No.	Recorded Plat	
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 7 03/08/2012 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(M11) Corner common to Sections 25-36 T52N-R36W and Sections 30-31 T52N-R35W. 1963 - Remonumented by
Billy D. Buckler RLS from Y.Birch B.T. S35E 29 links (dead stub with scribing) and Hemlock B.T. N30W
29 links (down). Original record indicates the Hemlock B.T. as "N22W 19 links". Set 1" ID I.pipe
with 4" brass cap. 12" Soft Maple S28E 24 links, 14" Soft Maple S42W 54 links.

(7-Sec. 25) North 1/16 corner between Section 25 T52N-R36W and Section 30 T52N-R35W. Not previously
monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M11) Found the 1963 monument as described, in good condition and at record bearing and distance
from the 1963 witnesses. The Maple SE NBT is a dead stub with scribing visible. The Maple SW NBT is
in good condition. The original B.T.s are no longer evident. Accepted the monument as a careful and
faithful perpetuation of the position of the original corner.

(7-Sec. 25) Established the position for the corner midway and on the Range line between Section
corner 1321.21' north and Quarter corner 1321.21' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M11) Fd. 1"ID I.pipe with 4" brass MI Dept.
of Conservation cap.
Set measuring nail with MDNR tag in the side of:
13" Maple S40W 36.5' old blazes and scribing
14" Y.Birch N05E 11.7' mrkd "S30 NBT"
8" Maple S30E 14.5' "S31 NBT"
9" Hemlock N74W 33.0' "S25 NBT"
Set sq'd cedar post adjacent.
Bearings are magnetic.

(7) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
14" Sugar N30E 6.6' mrkd "1/16S BT"
5" Sugar S61E 11.8' do
14" Hemlock S45W 5.9' do
8" Sugar N74W 10.9' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/26/2012

For the Michigan Department of Natural Resources, Forest Resources Division

