

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 53N R 32W	F1
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 4 T 53N R 32W	C-W-E-W 1/256
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No.	Recorded Plat	
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on 1/256 04/26/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F1) Quarter corner common to Section 4 T53N-R32W and Section 33 T54N-R32W. 1845 - Established by
Wm.A.Burt Deputy Surveyor 40.00 chains east of Section corner on the township line. Set post.
Hemlock 8 N59W 16 links, Fir 6 N16E 21 links. This corner was apparently recovered or reestablished
by W.W.Stockley, date unknown, who, according to previous certificates of record for 1/16 corners #4
and #8, subdivided this section and monumented those corners. No notes of the Stockley survey were
found by the undersigned.

(C-W-E-W 1/256 corner) Being the SW corner of the East 3/4 of the SE1/4 of the NW1/4 of Section 4.
Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F1) The original post and accessories were not recovered. Found no evidence of the position of the
original corner or its restoration on the ground. I reestablished the corner at a position which
best harmonizes with the existing monumentation of record defining the subdivision of Section 4 and
to make the whole of the North fractional 1/2 of the Section as regular as possible. The position
for the corner is 2637.51 ft. east (GLO rec. 2640 ft.) of monumented and recorded Section corner E1
and 2639.02 ft. north (GLO record 2640 ft.) north of the monumented and recorded Center of Section 4.

(C-W-E-W 1/256 corner) Established the corner on the E-W 1/4 line of Section 4 329.83' east of 1/16
corner #8 and 989.49' west of the Center of Section 4.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" W.Pine N27W 19.95' mrkd "1/4S NBT"
14" W.Pine N64E 8.2' do
7" Spruce S55E 11.3' do
5" Spruce S08W 1.95' do
Set sq'd Spruce post adjacent.
Bearings are magnetic.

1/256-Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
The cap is stamped to indicate land ownership -
MDNR lands being north and private lands south.
Set measuring nail with MDNR tag in the side of:
5" Y.Birch N20W 4.65'
7" Balsam N40E 1.4'
5" Y.Birch S05E 16.15'
12" Sugar S66W 21.05'
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 06/20/2011

For the Michigan Department of Natural Resources, Forest Management Division

