

APPROVED LAND CORNER
P.A. 348 OF 1990
Houghton County

Ronald W. Haataja
DEC. 10, 1997

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY &
REMONUMENTATION

SEP 17 1999

SECTION

For corners in
Houghton
(County)

Located in:

Corner Code #

NANCY FENILI 12/11/97

HOUGHTON COUNTY

11:23

LC 3/ 455 PAU Fee: 9.00

Page 1 of 1

1. Public Land Survey T55N R 32W
T55N R 32W
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Section S T R

Z3
D-3

Other #3

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Ronald S. Haataja in a field survey on November 19 97
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner Code (Z3) Meander Corner between Sections 5 and 8
42.86 Intersected Lake
4" Spruce Meander Corner
W. Birch 8" N57°E 271ks.

(D-3) S1/4 Corner Section 5, T55N-R32W
40.00 Set gr. Section Post
References: White Birch 6" S36°E 211ks.
Sugar 8" N75°W 151ks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Corner Code (Z3) Meander Corner between Sections 5 and 8
Found 1/2" pin with UPEA cap

(D-3) S1/4 Corner Section 5, T55N-R32W
No evidence of original survey found.
Set 3/4" I.D. Pipe at record distance from SE Corner Section 5

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner Code (Z3) Meander Corner between Sections 5 and 8
Accepted 1/2" capped pin as found corner. Drove 1" pipe
over pin and cemented brass remonumentation cap and stamped MC
Witnesses: 2" Apple N40°W 34.32', 4" Willow S71°W 33.27',
Property Corner 1/2" rebar S07°W 13.17', 6" Poplar S25°E
149.24', S1/4 Corner Sec. 5 N89°53'36"E 186.71'.
T55N-R32W

(D-3) S1/4 Corner Section 5, T55N-R32W
Set 3/4" I.D. Pipe and cemented brass remonumentation cap and stamped
Witnesses: Util. Pole N21°E 176.60', Util. Pole S87°E T55N-R32W
102.05', Util. Pole S54°E 203.80', 3/4" iron bolt S20°W
10.85' Meander Corner S89°53'36"W 186.71'.
T55N-R32W

Signed by Ronald S. Haataja

Date Nov. 25, 1997

1/4 COR.

Surveyor's Michigan License No. 39478

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	16	17	18	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

