

JAN 19 2001

SECTION

*Re-New Linder 2, Page 113*  
2000 REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For Corners in BINGHAM Township

Huron  
(County)

Located in:

Corner Code #

STATE OF MICHIGAN  
HURON COUNTY  
RECORDED

8 DEC 2000 9:58 AM

FRANCES L. HOLDWICK  
REGISTER OF DEEDS

1. Public Land Survey

T 15N R 13E  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_

A - 5

2. Property Controlling S  
in Section S

3. Miscellaneous S  
Property in Sec. S

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Russell L. Brown, in a field survey on June 9, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1834 G.L.O. H. Parke D.S. Set post corner Section 12 and 13, East side T15N-R12E,  
Pine 9 S3 1/2W 24, Hemlock 13 N31W 28

COUNTY SURVEYOR RECORD - None

COUNTY ROAD COMMISSION RECORD - Monument, WITNESSES: Spike S. Side 24" Elm N72°E 98.1', Iron Pin in fence N60°W 75.0' Spike N.E. side P.P. S40°E 50.3'; FOUND 5/8" Iron in Mon. Box, WITNESSES: S45°E 50.37' Spike in P.P., S45°W 53.55' Spike Top of corner post, N45°W 51.92' Spike in Corner Post

L.C.R.C. - None


RECORDED SURVEYS - continued next page

UNRECORDED SURVEYS - None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
No evidence of original corner or accessories found.

Found 5/8" Dia. Re-Rod in Monument Box.

Accepted found 5/8" Re-Rod as best evidence of original corner position.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A - 5, S. W. Cor. Sec. 7, N.W. Cor. Sec. 18, T15N-R13E

Found 5/8" Dia. Re-Rod in Monument Box

WITNESSES:

N45°E 38.00' 1/2" Dia. Re-Rod Set

N45°W 51.88' Spike in N.E. face of Corner Post

S45°W 53.43' Spike in Top of Corner Post

S45°E 50.40' Spike in N.E. face of Power Pole

South 2641.17' to A - 6, W. 1/4 Cor. Sec. 18, T15N-R13E

North 2638.89' to A - 4, W. 1/4 Cor. Sec. 7, T15N-R13E

NOTE

This corner is common with  
M - 5, T15N-R12E

Signed by Russell L. Brown  
Surveyor's Michigan License No. 24588

Date Nov. 2, 2000

Peer group approved at meeting held November 2, 2000. RLB

JAN 19 2001

SECTION

*Re - Mon Liber 2, Page 113.*

2000 REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For Corners in BINGHAM Township,  
Huron County, T15N-R13E  
A - 5 Continued

RECORDED SURVEYS:

3-22-77, Case Surveying, Stewert G. Case P.S. 15399, Liber 3 Surveys, Page 223 of Huron County Records.  
S. W. Cor. Sec. 7, T15N-R13E, Found 5/8" Steel Pin in Monument Box in Place

WITNESSES:

Spike in N.E. Side Power Pole, S50°E 50.30'  
Spike in S. W. Side Telephone Pole, N50°W 49.55'  
Spike in Top of Corner Post, S50°E 53.20'

1-31-80, Case Surveying, Stewert G. Case P.S. 15399, Liber 4 Surveys, Page 263 of Huron County Records.  
S. W. Cor. Sec. 7, T15N-R13E, Same witnesses as Liber 3 of Surveys, Page 223 of Huron County Records.

