

JAN 19 2001

SECTION

Re Mon. Liber 2, Page 72

2000 REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Huron

(County)

Located in:

Corner Code #

1. Public Land Survey Sand Beach T16NR 16E A-10
 T R
 T R
 T R
 2. Property Controlling S T R
 in Section S T R
 3. Miscellaneous S T R
 Property in Sec. S T R

STATE OF MICHIGAN
HURON COUNTY
RECORDED

20 SEP 2000 2:04 PM

FRANCES L. HOLDWICK
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, Charles S. Getz, in a field survey on July 18, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

A-10 1834 G.L.O., H. Parke D.S. County Road Commission Records - Large stone

Set quarter section post

Hemlock 24", S43°W, 7 Links

Cedar 8", N14°W, 30½ Links

Recorded Surveys - Case, 6-29-76, Liber 2, Page 651, 5/8" iron pin

Unrecorded Surveys - Case, 1-21-91, Certificate shows Corner

L.C.R.C. - NONE

County Surveyor Records -
NONE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-10

W 1/4 Cor, Section 30, T16N-R16E

Found no evidence of original corner position

Re-established corner position using a found survey iron and recorded bearings and distances shown on Case survey as Recorded in Liber 2, Page 651, as best evidence of original corner position for A-10.

(On Edwards Road)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-10

W 1/4 Cor, Section 30, T16N-R16E

Set 1/2" Re-Rod

West 75.15' to Nail in 6" Ash

S75°W 41.90' to Nail in Power Pole

S45°E 44.1' to North End of 36" Culvert

North 2661.48' to NW Cor, Sec 30, T16N-R16E

South 2601.80' to SW Cor, Sec 30, T16N-R16E

Signed by Charles S. GetzDate July 23, 2000Surveyor's Michigan License No. 25843

PEER GROUP APPROVED AT MEETING

HELD September 18, 2000. RLB