JAN 192001

HAMENTATION

RECTION

on Liker 2, Pege 11

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For Corners	in	CASEVILLE	Township
-------------	----	-----------	----------

Huron (County)	Located in: Corner Code #	STATE OF HICHIGAN HURON COUNTY
1. Public Land Survey	T 18N R 10E I-13	RECORDED
aziio zaiia oaivey	T 18N R 10E 1-13 TR	8 DEC 2000 9:58 AN
	T	
	T R	FRANCES L. HOLDWICK
2. Property Controlling S	T R	REGISTER OF DEEDS
in Section S	T	(100201011 0) 20020
3. Miscellaneous S	T R	
Property in Sec. \$	TR	Register of Deeds Stamp & File Number

4.	Lot No,	Recorded F	Plat
5.	Private Claims		

I, Russell L. Brown, in a field survey on October 12, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

OF MIC

RUSSELL L

Brown

LAND

SURVEYOR

NO.

COLAND

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration;

1834 GLO H. Parke D.S. Set post corner sections 34 and 35, T18N-R10E Pine 28 N40W 68; Y. Oak 7 N51 1/2E 83

Pine 28 N40W 68;

COUNTY SURVEYOR RECORD: None

COUNTY ROAD COMMISSION RECORD: None

L.C.R.C.: None

RECORDED SURVEY: Continued next page

UNRECORDED SURVEY: None

RECORDED PLATS: Continued next page

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original corner or accessories found.

Found 1" Pipe in Monument Box.

Accepted 1" Pipe as best evidence of original corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

I - 13, S. Comer common to Sections 34 and 35, T18N-R10E

Found 1" Pipe in Monument Box

WITNESSES:

West 3.90' to Centerline Asphalt surface Caseville Road

N40°W 66.62' to Spike in S.W. Side 16" Maple

S45°E 48.85' to Spike in S.W. Side 16" Maple

S50°W 31.60' to P.K. Nail in S.E. Side Utillity Pole

N45°E 35.98' to P.K. Nail in S. Side Utility Pole

East 2639.36' to J-13, S. 1/4 Cor. Sec. 35, T18N-R10E

West 2310,00' to Meander Corner between T17 & 18N-R10E

Deussell Signed by \ Surveyor's Michigan License No. 24588

Date <u>No</u>いる

Peer group approved at meeting held November 2, 2000.

THE MINISTER TATION

JAN 192001

Re mon Liker 2, Page 109.

RECTION

2000 REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 75, Mich. P.A. 1970

For corners in CASEVILLE Township,

Huron County, T18N-R10E

I - 13 Continued

RECORDED SURVEYS:

10-1-79, Case Surveying, Stewart G. Case P.S. 15399, Liber 4 survey, page 225 of Huron County Records. Southeast Corner Fractional Section 34, T18N-R10E
1" Iron Bar in place
WITNESSES:
Center Fire Hydrant, N45°E 44.65'
Spike in Southwest Side 14" Maple Tree, S55°E 48.55'
Southeast Corner American Legion Building, N50°W 85.20'

RECORDED PLATS:

1953, Grand Park Subdivision, Liber 4 of Plats on page 51 of Huron County Records. Shows N.W. Corner Section 2, T17N-R10E

1961, Galen W. Case P.S. 7431, Liber 6 of Plats on page 44 of Huron County Records. Grand Park Subdivision Number Two S.W. Cor. Sec. 35, T18N-R10E

No object stated and no witnesses given

