1999 REMONUMENTATION

Lider 2, Page 8 LAND CORNER RECORDATION CERTIFICA Filing Requirement of Act 76

Filing Requirement of Act 14, Mich. P.A. 1970										\mathcal{O}									
For Corners in Huron (County)		t		Corner Code #							ITE OF HURON REC		YTM	N					
1. P	ublic Land survey:	Hume		R 12_EB-13				29 NOV 2000 11:20 AH FRANCES L. HOLDWICK											
in 3. Mi	roperty Controlling Section iscellaneous roperty in Sec.	on S T R JAN 192001 Register o									REGISTER OF DEEDS								
4. Lo	ot Noivate Claims	, Recorded	Plat		SEC	HOH		_ _ 'i	A B	ç	p	E F	<u>6</u>	н	, <u>,</u>	ĸ	<u> </u>		
IJames TMeek, in a field survey onOctober 30, 19 99, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expessed below:								2 3 4 6 7 8	6 7 18		- 8 17 20			10	——————————————————————————————————————		13		
NOTE:	: Not more than on this certifica	_	ill in the s	ame town	and ran	ige, may be r	ecorded	10 11 12	30-	-	32 —	28-	-	27 —	26- 	+	-36		

A. Description of original monument and accessories and/or subsequent restoration: Original survey, South Bdy. T18NR12E, 1835,

Harvey Parke D.S.

B-13 South 4 Corner of Section 31 Post Hemlock 11", N88°E, 11 links Hemlock 28", N42°W, 22 links

County Surveyor's Record: none

Recorded Surveys: none

LCRC: none

C-13 Corner of Sections 31 and 32 Post

Sugar 30", N674°E, 30 links Beech 12", N614'W, 104 links

County Surveyor's Record: 1" gas pipe Recorded Surveys: L3, P197

LCRC: none

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

South 4 Corner of Section 31

Found 1" iron at centerline of Kinde Road. Occupation line bears north

Accepted as the best available evidence of the original corner position.

C-13 Corner of Sections 31 and 32

Found 4" iron at intersection of Pinnebog & Kinde Roads

Accepted as the best available evidence of the original corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner;

B-13 South 4 Corner of Section 31

C-13 Corner of Sections 31 and 32

1" iron in mon box

From which:

Tag in power pole bears North, 53.8'

½" iron bears N45°E, 26.0'

'" iron bears \$45°E, 25.0

b" iron bears \$45°W, 24.0'

%" iron in mon box

From which:

Tag in power pole bears N50°E, 66.5' NW cor building bears \$20°E, 59.0' Tag in power pole bears \$60°W, 67.3' Stop sign post bears N25°W, 46.2'

1" iron in mon box bears East, 225.65'

E OF MICHIG

Surveyor's Michigan License No. _39089

Date

MEEK No. 39089 PUED LAND SUF

RVEYORS, JAM. 28, 1971 REVISED MAY 14, 1975 REVISED JAM., 1983 REVISED OCT., 1986

RLB APPROVED AT PEER BOARD MEETING 11-02-00