

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

losco

(County)

Located In

Corner Code #

1. Public Land Survey

T 24N R 8E K-3
T 24N R 8E J-3

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Section

S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on December 18, 2006 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-3 G.L.O. J. Mullett and Wm. Burt 1843 set post for corner of sections 1,2,11 and 12

Wit: B. Ash 4" S04°E 07 links
B. Ash 6" N76°E 17 links

J-3 G.L.O. J. Mullett and Wm. Burt 1843 set quarter section post

Wit: Aspen 3" N22°W 08 links
Aspen 4" S67°E 06 links

July 1955 State Highway Department surveyor L.W. Slater found ¾" pipe 2 ½' below grade, raised with 1" pipe.

Wit: 5" Elm S55°E 74.33'
4" Elm S20°W 45.21'

Circa 1970 John C. Miller R.L.S. #7317 set a concrete monument for corner.

No witnesses were given.

Circa 1970 John C. Miller R.L.S. #7317 set concrete monument for corner. No witnesses were given.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-3 Found a broken concrete monument over a ¾" pipe 2.8' below grade fitting J.C. Miller's survey in section 2.

J-3 Found concrete monument fitting J.C. Miller's survey in section 2.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-3 Set 5/8" X 32" iron rod with P.S. cap #33981

Wit: P. Pole S75°W 15.86'
5" Balsam N27°W 64.68'
6" Elm N63°E 119.12'
12" Apple S59°E 10.74'
Centerline of private drive going West

J-3 Found Concrete monument

Wit: 11" Maple N20°W 5.75'
24" Red Pine N83°E 13.13'
13" Maple S65°E 37.62'
12" Maple S27°W 11.63'
Single wire fence going North

Signed by:

Carl T Kiiskila

Date:

4-4-07

Surveyor's Michigan License No.:

33981

