

FEB 16 1999

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners IOSCO Located In: \_\_\_\_\_ REMONUMENTATION CORNER  
Corner Code # \_\_\_\_\_

1. Public Land Survey T 24N R 9E 6  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

98-55

STATE OF MICHIGAN  
IOSCO COUNTY  
FILED

10 DEC 98 2:56 P.M.

RONITA M. COYLE  
REGISTER OF DEEDS

5. Private Claims \_\_\_\_\_

I, WILLIAM E. WOODS P.S., in a field survey on NOV 17, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:  
1843: ORIGINAL GOVERNMENT NOTES SET POST

22" Y. PINE S 35° E 36 LK.  
22" Y. PINE S 35° W 27 LK.

1994: NORTHEAST LAND SURVEYS

BOUNDARY SURVEY SHOWS FOUND CONCRETE MONUMENT  
9.4" WEST OF SECTION LINE AS MONUMENTED AT SHORE OF  
LAKE 1129.40 NORTH OF 1/4 CORNER. DEED RECORDED IN LIBER  
208 PAGE 217 REFERS TO MEANDER POST SET BY ROY. J ROBB, R.S.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND CONCRETE MONUMENT 1129.4 FEET NORTH OF 1/4 CORNER ON LAKE SHORE  
I USED IT AS A WITNESS CORNER WHICH IS 49.60 FEET NORTH OF ORIGINAL MEANDER CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner  
FOUND MONUMENT IN GOOD CONDITION AT LOCATION SHOWN ON SURVEY.

N.E. CORNER CONCRETE SEAWALL N 45° W 18.90  
20" W.PINE S 70° W 24.80  
12" R. OAK S 30° W 19.36  
12" R. OAK S 50° E 27.35  
NORTH EDGE 3.5" SEAWALL & WATER EDGE 14.11

ACCEPTED BY THE IOSCO COUNTY  
SURVEY PEER GROUP AS THE  
OFFICIAL CORNER UNDER P.A.  
345 OF 1990 AT A MEETING  
HELD ON 9-22-98

*James H. Chandler*

Signed by

*William E Woods*

Date

12-9-98

WILLIAM E. WOODS P.S.

Surveyor's Michigan License No. 25882

