

LAND CORNER RECORDATION CERTIFICATE REMONUMENTATION

Filing Requirement of Act 74, Mich. P.A. 1970

FEB 15 2001

For corners in IOSCO Located In: _____ Corner Code # _____

1. Public Land Survey T 24N R 9E I-J5 #11
 T _____ R _____ Reference Corner
 T _____ R _____
 T _____ R _____
 T _____ R _____
 T _____ R _____
 2. Property Controlling S _____
 in Section S _____
 T _____ R _____
 T _____ R _____
 3. Miscellaneous S _____
 Property in Sec. _____
 4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, WILLIAM E. WOODS P.S.; in a field survey on OCT. 16, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1843: ORIGINAL GOVERNMENT NOTES

SET POST

W. PINE 12" N30°W 27 LKS.
 TAMARACK 8" S47°W 63 LKS.

ACCEPTED BY THE IOSCO COUNTY
 SURVEY PEER GROUP AS THE
 OFFICIAL CORNER UNDER P.A.
 345 OF 1990 AT A MEETING
 HELD ON 10-11-2000

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1949: CLARENCE F. AIKMAN

LAKE HURON SAND BEACH SUBDIVISION NO. 2
 PLAT COMMENCES AT I-5, SHOWS SECTION LINE
 GOING THROUGH LOT 337

2000: WILLIAM E. WOODS

MEASURED 8 CHAINS 528 FEET EAST OF I-5, CORNER
 FALLS IN SOUTH-BOUND LANE OF U.S. 23 250 FEET WEST OF
 WATERS EDGE OF LAKE HURON SET REFERENCE CORNER ON
 WESTERLY RIGHT-OF-WAY U.S. 23 449.00 FEET EAST OF I-5,
 AND 79.0 FEET WEST OF MEANDER CORNER

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

5/8" BAR & REMON CAP REFERENCE CORNER ON WESTERLY RIGHT-OF-WAY U.S. 23 449.00 FEET EAST OF I-5, AND 79.0 FEET WEST OF MEANDER CORNER

SPRUCE 3" N40°E 61.27' P.K. & TAG
 MAPLE 18" N17°W 20.15' NAIL & TAG
 S.E. CORNER MAIN PART OF HOUSE #7005 N75°W 32.62'
 S.E. CORNER GARAGE CONCRETE BLOCK FOUNDATION S67°W 50.0'
 P.K. W. EDGE SOUTH BOUND LANE EAST 78.99'

Signed by

William E Woods

WILLIAM E. WOODS P.S.

Surveyor's Michigan License No. 25882

Date

12-06