

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 10 T 41N R 31W	1
	S T R	(GCDB 420600)
	S 10 T 41N R 31W	4
	S T R	(GCDB 420560)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 02/02/16 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 10) West 1/16 corner between Sections 3 and 10. Not previously monumented.

(4-Sec. 10) Northwest 1/16 corner, Section 10. Found no record of prior monumentation.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-Sec. 10) Established the corner midway and on the Section line between Section corner 1325.43'
west and Quarter corner 1325.43' east.

(4-Sec. 10) Found a 5/8" diameter rebar with plastic cap "Stevens MI 46690 WI S-2467-008"
substantially at the intersection of straight lines connecting opposite 1/16 corners and accepted
same as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" Maple N24°E 6.45' mrkd "1/16S BT"
13" Hemlock S36°E 10.8' do
11" Hemlock S51°W 9.95' do
12" Hemlock N70°W 20.3' do
Set sq'd cedar post adjacent.
E= 7908991.519 N= 132709.355

(4) Found 5/8" capped rebar.
Set measuring nail with MDNR tag in the side of:
8" Cedar N57°E 14.25' old blaze 10yr+/- old
12" Cedar N41°W 7.8' do
7" Cedar S39°E 19.6' mrkd "1/16S BT"
4" B.Ash S02°E 11.5' do
Set sq'd cedar post adjacent.
E= 7908987.348 N= 132305.155

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum
Coord. Ref.=NGS PID RL0240: N= 145070.966 m. E= 7907633.632 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 02/25/2016

For the Michigan Department of Natural Resources, Forest Resources Division

