

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 2 T 42N R 31W	3
	S T R	(GCDB 500660)
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 07/07/14 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(3-Sec. 2) North 1/16 corner between Sections 2 and 3. 1974 - Established by A.O.Enger RLS on line  
between 1/4 corner 20.137 ch. South and Section Corner 19.462 ch. North. Set 1"IDx36" I.pipe with  
3.5" dia. alum. cap. Red Pine stump 16" N43°E 11.1'; W.Pine stump 16" S72°E 9.5'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(3-Sec. 2) Found the 1974 monument in good condition and substantially at the record position,  
1328.70' north of 1/4 corner and 1283.48' south of Section corner, and 0.07' west of a straight line  
between them. Accepted the monument as a careful and faithful establishment of the position of the  
corner. The 1974 witnesses were not recovered.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 1"ID I.pipe with 3.5" alum. State of Michigan  
cap. Set measuring nail with MDNR tag in the side  
of:

5" double Cherry N56°E 15.1' mrkd "1/16S BT"  
13" Poplar S81°E 51.45' do  
3" R.Pine S05°E 72.4' do  
4" Cherry in clump S47°W 82.25' do  
Set sq'd cedar post adjacent.  
E= 7910318.783 N= 143585.903



Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).  
Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.634 m.

Signed by Stephan J. Szyszkoski Date 07/07/2014  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division