

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 1 T 42N R 31W	2
	S T R	(GCDB 660700)
	S 2 T 42N R 31W	5
	S T R	(GCDB 540660)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Stephan J. Szyszkoski, in a field survey on 5 04/23/14
2 04/22/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(2-Sec. 1) East 1/16 corner between Section 1 T42N-R31W and Section 36 T43N-R31W. Not previously
monumented.

(5-Sec. 2) Center-North 1/16 corner, Section 2. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(2-Sec. 1) Established the position for the corner midway and on the Township line between Township corner 1317.38' East and 1/4
corner 1317.38' West.

(5-Sec. 2) Established the position for the corner on a straight line between 1/4 corner 1277.71'
north and the intersection of 1/4 lines of Section 2 1325.42' south, the position being
proportionate to the dimensions derived from the original U.S. plat of this township.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(2) Set 1"IDx28" I.pipe w/2" dia. alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Spruce S64°W 34.1' mrkd "1/16S BT"
6" Spruce N30°W 8.4' do
7" Spruce N54°E 7.1' do
4" Spruce S83°E 52.8' do
Set sq'd cedar post adjacent.
E= 7913144.563 N= 143918.651

(5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Cedar N29°E 11.4' mrkd "1/16S BT"
7" Cedar S86°E 3.55' do
9" Cedar S02°E 12.35' do
6" Cedar N69°W 7.7' do
Set sq'd cedar post adjacent.
E= 7911122.436 N= 143572.999

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.634 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 05/07/2014

For the Michigan Department of Natural Resources, Forest Resources Division

