

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 2 T 42N R 31W	15
	S T R	(GCDB 520600)
	S 12 T 42N R 31W	1
3. Miscellaneous Property in Sec.	S T R	(GCDB 620600)
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 04/15/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(15-Sec. 2) West 1/16 corner between Sections 2 and 11. 1974 - Established and monumented by A.O.Enger RLS on line between Section corner 19.934 ch. West and 1/4 corner 19.935 ch. East. Set 1"IDx34" I.pipe with 3.5" aluminum cap. Aspen 6" S33°W 13.9', Aspen 6" East 40.5'.

(1-Sec. 12) West 1/16 corner between Sections 1 and 12. 1974 - Established and monumented by A.O.Enger RLS on line between Section corner 20.060 chains West and 1/4 corner 20.060 chains East. Set 1"IDx36" I.pipe with 3.5" aluminum cap. W.Pine 10" N12°W 75.1', W.Birch 13" in clump S61W° 79.8'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15-Sec. 2) Found the 1974 monument in good condition and substantially at the record position. The 1974 witnesses were not recovered. Accepted the monument as a careful and faithful establishment of the position of the corner.

(1-Sec. 12) Found the 1974 monument in good condition, substantially at the record position, and at record bearing and distance from the 1974 W.Pine BT. Accepted same as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Found 1"ID I.pipe with 3.5" alum. State of Michigan cap. Set measuring nail with MDNR tag in the side of:

10" R.Pine N50°W 57.7' mrkd "1/16S BT"
9" Maple N29°E 45.4' do
11" W.Pine S60°E 21.0' do
9" Maple S59°W 34.3' do
Sq'd cedar post adjacent.
E= 7910704.751 N= 142366.099

(1) Found 1"ID I.pipe with 3.5" alum. State of Michigan cap. Set measuring nail with MDNR tag in the side of:

24" W.Pine N07°W 75.1' old blazes (1974 BT)
7" Oak N72°E 16.7' mrkd "1/16S BT"
7" Poplar South 7.25' do
5" R.Pine S67°W 40.3' do
Set sq'd cedar post adjacent.
E= 7912310.822 N= 142344.042

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.634 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 05/07/2014

For the Michigan Department of Natural Resources, Forest Resources Division

