

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 42N R 35W	L-7
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

CO DEC -8 PM 1:11

L.C. Records: L-8, P. 297

G. L. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Quarter Corner to Sections 13 and 24, T42N, R35W

I, Gary L. Pisoni, in a field survey on November 24, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on August 11, 1851 by Harvey Mellen, U.S. Deputy Surveyor.

Original Corner: Wood Post

Original Bearing Trees:

Yellow Birch	10"	N 48°E	19 links (12.54 feet)
Sugar	18"	N 32°W	34 links (22.44 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Iron Spike in Centerline of Road

PEER GROUP APPROVED
Gary L. Pisoni 11-29-2000
COUNTY REPRESENTATIVE

No evidence of original B.T.s found.

In 1987, I restored the corner position with a railroad spike in the centerline of an East/West County road and a fence line running South. Distances East and West are consistent with GLO distance.

I accept the railroad spike as the best available evidence for restoring the corner position.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set one reference monument being a 5/8" diameter by 30" long rebar pin with a 3" diameter aluminum cap stamped as follows:
Iron County Remonumentation, T42N, R35W, R.M., 1/4, S-13, S-24, North, 15.75 feet, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees: (All measurements taken to a nail in side of tree)

R.M.	5/8" x 30" rebar	South	15.75 feet
Sugar Maple	11"	S 31°W	61.08 feet
Sugar Maple	7"	N 18°W	63.69 feet
Utility Pole	#80-24475	N 78°E	110.55 feet
Steel sign post		South	15.2 feet

00-065

Signed by Gary L. Pisoni Date 11-29-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JULY 28, 1971
REVISOR MAY 14, 1975
REVISOR JAN. 1983
REVISOR OCT., 1995

