LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

			1
Iron	Located In:	Corner Code #	
(County)			i.e
1. Public Land Survey	T R R		
2. Property Controlling in Section	S 18 T 43N R 31W S 18 T 43N R 31W	5 B6	\
3. Miscellaneous Property in Sec.	S T R S T R S T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R		
4. Lot No. , Recorded Plat Register of Deeds Stamp & File Number			
5. Private Claims			ABCDEFGHIJKLM
			2 6 5
I, Stephan J. Szyszkoski , in a field survey on 03/06/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2			
above were in conformance with regulations and rules therefore as required in the current manual of survey 5 instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6			
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7			
the rules of the Michigan Boar re-established, monumented, recov	d of Land Surveyors or by a Decree	of a Court of Law; established,	9 20 21 22 23 24
NOTE: Not more than 2 core	pers all in the same town and		10 30 29 28 27 26 25
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			
and the same of th			12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:			

- (B6) Center of Section 18. Not previously monumented.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 18) North 1/16 corner, Section 18. Not previously monumented.

(5-Sec. 18) Established the position for the corner midway and on a straight line between Quarter corner 1325.03' north and the Center of Section 18 1325.03' south.

- (B6) Established the position for the corner at the intersection of straight lines connecting opposite 1/4 corners.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (5) Set 1"IDx32" I.pipe with 4" alum. MDNR cap made firm in a mound of rock 3' dia. By 2' high. Set measuring nail with MDNR tag in the side of:
 4" Balsam N73°E 4.65' mrkd "1/16S BT"
 4" Sugar S69°E 7.3' do
- 4" Sugar S46°E 6.5' do 6" Balsam N24°W 23.4' do
- E= 7904784.016 N= 150095.493

- (B6) Set 5/8"x28" rebar with yellow plastic MDNR cap. Set measuring nail with MDNR tag in the side of:
- 2" W.Spruce N22°E 12.1'

mrkd " X X "

2" W.Spruce N61°E 13.3' 8" Cedar S29°W 26.15'

"C1/4 BT"

9" Cedar N66°W 22.0'

do

Set sq'd cedar post adjacent. E= 7904782.755 N= 149691.689

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum) Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.635 m.

Signed by Stepher.
Surveyor's Michigan License No.

Synsyhorl.

Date

07/18/2013

For the Michigan Department of Natural Resources, Forest Resources Division

SOURCES DIVISION

FORM APPROVED BY MICHIGAN STATE BOARD OF PROPESSIONAL