

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>43N</u> R <u>31W</u>	<u>C.D-7e</u> <u>(008)</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

COMMONWEALTH YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC 22 PM 3: 26

L.C. Records: L. 8, P. 316

William J. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

East Meander Corner Between Sections 17 and 20, T43N, R31W

I, Gary L. Pisoni, in a field survey on December 1, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on July 14, 1849 by John Burt, U.S. Deputy Surveyor.

Original Corner; Cedar Post

Original Bearing Trees:

Cedar	12"	N 20° E	23 links (15.18 feet)
Cedar	12"	S 28° E	24 links (15.84 feet)

On 5/9/74, Arthur O. Enger, RLS DNR re-established the meander corner position by setting an auxiliary meander corner on line between the Northwest corner of Section 20 and the North quarter corner of Section 20; set a 1" diameter by 36" long iron pipe with a 3 3/4" diameter aluminum cap stamped as follows: T43N, R31W, Aux. M.C., S-17, S-20, 5/9/74, RLS 13581
No bearing trees found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Found monument as described above.

Corner located on the East bank of the Michigamme River (now a pond) and is 14' from waters edge. Actual river is approximately 350' East, river was relocated around 1900.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (all measurements taken to a nail in side of tree)

Ash	6"	N 63° E	61.66 feet
Ash	6"	S 84° E	42.66 feet
Cedar	8"	S 38° E	79.86 feet
Steel sign post		East	0.65 feet

00-084

Signed by


Gary L. Pisoni

Date

12-19-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971
27457 REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995



LIBER

8 PAGE 316