

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC 22 PM 3: 24

L.C. Records: L. 8, P. 301

Gary L. Pisoni
REGISTERED PROFESSIONAL SURVEYOR

Register of Deeds Stamp & File Number

_____ Iron _____ Located In: _____ Corner Code # _____
(County)

1. Public Land Survey T 43N R 31W E-10
T _____ R _____
T _____ R _____
T _____ R _____

2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____

3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Quarter Corner Between Sections 29 and 28, T43N, R31W

I, Gary L. Pisoni, in a field survey on December 5, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on July 17, 1849 by John Burt, U.S. Deputy Surveyor.

Original Corner; Cedar Post

Original Bearing Trees:

Cedar	8"	N 51° E	22 links (14.52 feet)
Spruce	10"	S 31° W	7 links (4.62 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Found picket and tag which bears N 17°54'W, 70.14 feet from corner position.

Restored the corner position by single proportionate measurement and on line between the Northwest and Southwest Section corners of Section 28.

Corner record research on file with County Representative.

PEER GROUP APPROVED

Gary L. Pisoni 12-20-2000
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, set a 5/8" diameter by 30" long rebar pin with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T43N, R31W, 1/4, S-29, S-28, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

Cedar	11"	N 38° E	27.84 feet
Cedar	10"	S 60° E	5.44 feet
Cedar	8"	S 06° E	26.56 feet
Cedar	9"	N 50° W	14.51 feet
Steel sign post		N 08° W	0.85 feet

00-069

Signed by Gary L. Pisoni Date 12-19-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

