

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u>	Located In:	Corner Code #
(County)		
1. Public Land Survey	T <u>43N</u> R <u>R31W</u>	<u>H-11</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:11

L.C. Records: L.S.P. 295

Gary L. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Quarter Corner to Sections 27 and 34, T43N, R31W

I, Gary L. Pisoni, in a field survey on October 26, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on July 27, 1849 by John Burt, U.S. Deputy Surveyor.

Original Corner; Yellow Birch Post

Original Bearing Trees:

Yellow Birch	12"	N 57° E	25 links (16.50 feet)
Cedar	16"	S 35° W	6 links (3.96 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Restored the corner position at the intersection of the centerline of M-69 which runs East and West and the centerline of Dawson Lake Road which runs South.

I accept this position as the best available evidence for restoring the corner position.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position set a P.K. nail in the centerline of M-69 and set two (2) reference monuments being a 5/8" diameter by 30" long rebar pin with a 3" diameter aluminum cap stamped as follows:

Iron County Remonumentation, T43N, R31W, R.M., 1/4, S27, S-34, S 35° E, 63.04 feet, 2000, RLS 27457;
T43N, R31W, R.M., 1/4, S-27, S-34, S 34° W, 86.55 feet, 2000, RLS 27457 from which I established the following new corner references:

R.M.	5/8" x 30" rebar	N 35° W	63.04 feet
R.M.	5/8" x 30" rebar	N 34° E	86.55 feet
Rebar	5/8" x 30"	S 36° E	81.90 feet
Rebar	5/8" x 30"	S 55° W	184.64 feet
Steel sign post		N 35° W	63.95 feet
Steel sign post		N 34° E	87.50 feet

00-063

Signed by Gary L. Pisoni

Date 11-27-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1991

REVISED OCT., 1995

