## SURVEY & REMONUMENTATION

## FEB 21 2001

## SECTION

## LAND CORNER RECORDATION CERTIFICATE

	Filing	Requirement of	ACT /4, MICH. P.A. T	970			
For corners in			· I	COMMEN	CING YEAR 20	203	
			orner Code #	RECEIVI	ED FOR RECO	RD	
lron	Located In:	C	orner Code #	IRON CO	UNTY, MICHIG	AN	
(County)				DO DEO	D DU .	•	
1. Public Land Survey	T <u>43N</u> R <u>3</u>	34WG	j-9	ייס חבר.	-8 PH 1:	U9	
	TR_			L.C. Ker	iouls:L.	Š, P. Q8 J	12
	T R_			ه رسیس	A STATE		
	T R_			Godelin	ne afterde	J	
2. Property Controlling	S R_			con ut to 2.	en the acous	i	
in Section	S	<del></del>					
3. Miscellaneous	S					0 E11- March	
Property in Sec.	S R_			Registe	r of Deeds St	amp & File Nur	11001
_							
4. Lot No, R	ecorded Plat		<del></del>	A B C	DEF G	H I J K	L I
5. Private Claims				2 6	_5 _ 4 _	3	· 1·
Section Corner to Sections	- 21 22 27 28 T43N	R34W		3	Ĭ i		
Section Corner to Sections	, 21, 22, 27, 20, 1451	, 110-111		, ,			
I, Gary L. Pisoni .	in a field survey on	September 12	, 2000 do hereby state	4 ?	- 8 9 1	-1011	12
that under requirements of	if P.A. 74. Michigan P.A	<ol> <li>of 1970, the co</li> </ol>	rner points mentioned	5			
in lines 1 and 2 above 1	were in conformance v	with regulations a	and rules therefore as	6 -18-	1716	15	13
required in the current ma	nual of survey instructi	ons of the United	States Department of	7		_   _   -	
the Interior, Bureau of Lan	d Management or by a c	lecree of a Court	of Law and for that the	8 19-	2021	2223	24
corner points mentioned in the Michigan Board of La	n lines 3, 4 and 5 above	necree of a Cour	t of law: established.			. T   T	
re-established, monument	and surveyors or by a manager and as	expressed below:	( or Early columniation)	9		<b>'</b>	
Te-established, monument	54, 1000 (0104) (0314 40			10-30-	2 <sup>9</sup> -  2 <sup>8</sup>	_2726	2 <sup>5</sup>
NOTE: Not more than 2 co	orners, all in the same town	n and range, may be	recorded	11			
on this certificate.				12-31	3233	3435	36-
				13			
Original corner estable Original Corner; Wood	ished on September 1, d Post	1851 by Guy H. C	Carleton, U.S. Deputy S	Surveyor.			
Original Bearing Trees		N 000F	15 Univ. (0.00 fact)		PEER GROUP APPROVED		
Yellow Birch Cedar	າ 30" 16"	N 32°E S 66°W	15 links (9.90 feet) 21 links (13.86 feet)		I'Ron stang	L. From 11	80-
					COUNTY	REPRESENTA	TIVE
	r evidence found and/or	method applied ii	i restoring or reestablis	many comor.	•		
No evidence of origin				:-! <b></b> -	and Mast coi	hateool ain b	
Found an iron pin ma 2" below blacktop s	arking corner position lo urface. Iron pin is locat	ecated in the cent led on a fence line	erline of Old U.S. 2 Wh e running North.	ion runs East	and west, sa	a piii locatea	
I accept the iron pin	as the best available ev	vidence for restori	ng the corner position.				
Corner record research	ch on file with County F	Representative.	•				
C. Description of monu	ment for corner and acc	essories establish	ed to perpetuate locati	ng the positio	n of the corne	er:	
Set one reference me	onument being a 5/8" d	iameter by 30" lo	ng rebar pin with a 3"	diameter alum	ninum cap sta	mped as follow	ws: ch l
Iron County Remonu	mentation, T43N, R34V wing new blazed and so	rihed bearing tree	s: (All measurements t	aken to a nail	in side of tree	e)	
established the follow Rebar (Cole		North	32,98 feet				
Ash	9"	N 36° E	41.79 feet				
R.M.	5/8" x 30" rebar	South	21.83 feet			letter.	
Utility Pole		S 24° W	31,59 feet		MILL OF	MICHINE	
Ash	14"	N 63° W	78.90 feet 22.8 feet		HATE	GAN	
Steel sign <sub>I</sub>	Jeoc	South	44.0 1661		GAF	Y L.	
00-050	10			:	⊁ PIS	INOS	Ç Ž
Signed by Tang	Fison	Date/(~	13-2000		Li	AND 💢	E C
• • • • • •	No 07457		FORM APPROVED BY N		SUR'	/EYCM LSURVEYORS, JAN. :	2 <b>8.</b> 1971
Surveyor's Michigan Lice	ense No. <u>27457</u>		COUNT MELUCATED BY IN		Co. 27	1457 REVISED MAY	C14, 13/3
					3, 57	BEVISED O	
					TIN TED	LAND	
		HEP	R DAGE R	9	··um	131111111111111	