

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970 as Amended**

For corners in

Iron	Located In:	Corner Code #
(County)		
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 4 T 44N R 31W	7
	S 4 T 44N R 31W	16
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 7 09/26/2011 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

(7-Sec. 4) North 1/16 corner between Sections 3 and 4. Not previously monumented. The original plat shows this corner to be 20.00 chains north of the Quarter corner and 19.55 chains south of the Section corner.

(16-Sec. 4) East 1/16 corner between Sections 4 and 9. Not previously monumented.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

(7-Sec. 4) Established the position for the corner on the Section line between Quarter corner 1322.46' south and Section corner 1292.71' north, being proportionate to the dimensions given on the original plat of this township.

(16-Sec. 4) Established the position for the corner midway and on the Section line between Section corner 1327.79' east and Quarter corner 1327.79' west.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

(7) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
 2" W.Birch N34E 14.1' mrkd " X X "  
 2" Maple N02W 4.9' do  
 7" Spruce S89E 50.1' "1/16S BT"  
 8" Spruce S42E 5.8' do  
 Set sq'd cedar post adjacent.  
 Bearings are magnetic.

(16) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
 7" Sugar S81E 10.0' mrkd "1/16S BT"  
 4" twin Sugar S14E 22.7' do  
 6" Sugar S26W 23.9' do  
 5" Sugar N28W 11.75' do  
 Set sq'd Cedar post adjacent.  
 Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
 Surveyor's Michigan License No. 33986

Date 01/19/2012

For the Michigan Department of Natural Resources, Forest Management Division

