

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 14 T 44N R 31W	3
	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 02/26/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(3-Sec. 14) North 1/16 corner between Sections 14 and 15. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(3-Sec. 14) Established the position for the corner midway and on the Section line between Section
corner 1322.55' north and Quarter corner 1322.55' south. The position for the corner falls in
Shiner Lake and was not monumented directly. I established two WITNESS CORNERS to the corner
position - the first on the North 1/16 line of Section 14 183.00' east of the corner position and
the second on the Section line 444.00' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

WC 183.00' east of the corner position.
Set 1"IDx32" I.pipe with 4" alum. MDNR cap
Set measuring nail with MDNR tag in the side of:
19" W.Pine N22°W 12.85' mrkd "WC BT"
4" B.Spruce N04°E 18.65' do
10" W.Pine S68°E 12.45' do
13" W.Pine S46°W 6.0' do
Set sq'd Cedar post adjacent.
E=7910623.512 N=159676.737

WC 444.00' south of the corner position.
Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
3" B.Spruce N13°E 19.65' mrkd "WC BT"
5" B.Spruce S62°E 8.4' do
4" Tamarack S79°W 9.95' do
4" Tamarack N61°W 0.9' do
Set sq'd Cedar post adjacent.
E=7910564.383 N=159542.673

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=NGS PID RL0202: N= 156159.380 m. E= 7917031.363 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 05/15/2013

For the Michigan Department of Natural Resources, Forest Resources Division

