

# LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: See below

For corner(s) in: Iron County

## Original Public Land Survey Corner

## Corner Code

S          T          R           
S          T          R           
S          T          R           
S          T          R         

## Property Corner

## 1/16 Corner Code

a. S 11 T 44N R 32W 9 (GCDB 560540)  
S          T          R           
b. S 22 T 44N R 32W 6 (GCDB 460360)  
S          T          R         

|    |   |    |   |    |   |    |   |    |   |    |   |    |   |    |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|----|
| 1  | A | B  | C | D  | E | F  | G | H  | I | J  | K | L  | M | 1  |
| 2  |   | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   | 2  |
| 3  |   |    |   |    |   |    |   |    |   |    |   |    |   | 3  |
| 4  |   | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   | 4  |
| 5  |   |    |   |    |   |    |   |    |   |    |   |    |   | 5  |
| 6  |   | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   | 6  |
| 7  |   |    |   |    |   |    |   |    |   |    |   |    |   | 7  |
| 8  |   | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   | 8  |
| 9  |   |    |   |    |   |    |   |    |   |    |   |    |   | 9  |
| 10 |   | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   | 10 |
| 11 |   |    |   |    |   |    |   |    |   |    |   |    |   | 11 |
| 12 |   | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   | 12 |
| 13 | A | B  | C | D  | E | F  | G | H  | I | J  | K | L  | M | 13 |

## Part A. Corner History

a. Center-East 1/16 corner, Section 11 T44N-R32W. Not previously monumented.

b. Northeast 1/16 corner, Section 22 T44N-R32W. Not previously monumented.



## Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a. April 25, 2018. Established the position for the corner midway and on a straight line between Quarter corner 1309.11' east and the intersection of 1/4 lines of Section 11 1309.11' west. The position for the corner falls about 12' east of the center of Deer Foot Lodge Road.

b. May 2 2018. Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners, those to the north, east, and west being monumented.

## Part C: Field Evidence of Perpetuation or Monumentation of Corner

a. Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
12" Tamarack N43°E 26.55' mrkd "1/16S BT"  
3" W.Birch S48°E 20.5' do  
11" Spruce S34°W 54.4' do  
16" Tamarack N55°W 65.1' do  
E= 7902153.96 N= 161018.61

b. Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
3" Sugar S82°E 19.0' mrkd "1/16S BT"  
3" Sugar S14°E 19.5' do  
10" Sugar S70°W 22.0' do  
8" Sugar N40°W 3.65' do  
Set sq'd cedar post adjacent.  
E= 7900493.47 N= 158228.26

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.

Stephan J. Szyszkoski 05/30/2018

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908